

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

03/02/2018

Submitted Date:

03/06/2018

Document Number:

674902087**FIELD INSPECTION FORM**
 Loc ID 326281 Inspector Name: Hughes, Jim On-Site Inspection ☐ 2A Doc Num: _____
Operator Information:OGCC Operator Number: 10663Name of Operator: ENDURING RESOURCES LLCAddress: 511 16TH STREET #700City: DENVER State: CO Zip: 80202**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:13 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
McDaniel, James	505-444-3004	jmcdaniel@enduringresources.com	SW Inspection Reports
Fischer, Alex		alex.fischer@state.co.us	
Pohl, April	505-636-9722	apohl@enduringresources.com	SW Inspection Reports

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
216163	WELL	PR	03/13/2001	GW	067-07769	BURNETT 2-1	EI

General Comment:

On March 2, 2018 COGCC SW EPS Jim Hughes conducted an environmental field inspection of the Enduring Resources LLC Burnett #2-1. For the most recent field inspection report of this facility, please refer to document #674601284.

Location				
Lease Road:				
Type	Access			
comment:				
Corrective Action	L		Date:	
Overall Good: <input checked="" type="checkbox"/>				
Signs/Marker:				
Type	TANK LABELS/PLACARDS			
Comment:	Placard mounted to catwalk over secondary containment berm. Labels and placards directly on tank.			
Corrective Action:			Date:	
Type	WELLHEAD			
Comment:	Free standing sign near location entrance.			
Corrective Action:			Date:	
Emergency Contact Number:				
Comment:	Posted on location sign.			
Corrective Action:				Date: _____
Overall Good: <input type="checkbox"/>				
Spills:				
Type	Area	Volume		
In Containment: No				
Comment:				
<input type="checkbox"/> Multiple Spills and Releases?				
Fencing/:				
Type	LOCATION			
Comment:	Perimeter chain link fencing around location.			
Corrective Action:			Date:	
Type	PUMP JACK			
Comment:	Guard fencing.			
Corrective Action:			Date:	
Equipment:				
Type: Vertical Heated Separator	# 1			corrective date
Comment:				
Corrective Action:			Date:	
Type: Ancillary equipment	# 1			
Comment:	Electrical supply equipment.			
Corrective Action:			Date:	
Type: Gas Meter Run	# 1			
Comment:				
Corrective Action:			Date:	

Type: Pump Jack	# 1	
Comment:	Electric motor.	
Corrective Action:		Date:
Type: Bird Protectors	# 1	
Comment:		
Corrective Action:		Date:
Type: Deadman # & Marked	# 4	
Comment:		
Corrective Action:		Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	<100 BBLs	PBV STEEL		37.234572,-107.818511
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)	95 bbl.	
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

Venting:

Yes/No		
Comment:		
Corrective Action:		Date:

Flaring:

Type	
Comment:	
Corrective Action:	Date:

Inspected Facilities									
Facility ID:	216163	Type:	WELL	API Number:	067-07769	Status:	PR	Insp. Status:	EI

--

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass					
Compaction	Pass					
Waddles	In Process	Compaction	Pass	Material Handling And Spill Prevention	Pass	Drip pot on load out line.

Comment: [Monitor erosion along western edge of location.](#)

Corrective Action:

Date: _____

Pits: ☒ NO SURFACE INDICATION OF PIT**COGCC Comments**

Comment	User	Date
On March 2, 2018 COGCC SW EPS Jim Hughes conducted an environmental field inspection of the Enduring Resources LLC Burnett #2-1. For the most recent field inspection report of this facility, please refer to document #674601284.	hughesj	03/06/2018

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
674902088	Inspection Photos.	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4394577