

**Inspection Photos**  
**Location Name: Royce State #36-2**  
**API: 05-067-07473**



**Royce State #36-2 pump jack and well head.**



**Unused section of flex pipe on southern edge of location.**



**Inspection Photos**  
**Location Name: Royce State #36-2**  
**API: 05-067-07473**



**Storm water BMP in disrepair.**



**Wattles along southern edge of location have filled in with sediment.**

**Inspection Photos**  
**Location Name: Royce State #36-2**  
**API: 05-067-07473**



**Lube oil container with secondary containment and leaking generator.**



**Lube oil leaking from equipment.**