

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

03/02/2018

Submitted Date:

03/06/2018

Document Number:

674902089**FIELD INSPECTION FORM**Loc ID 326101 Inspector Name: Hughes, Jim On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 10663Name of Operator: ENDURING RESOURCES LLCAddress: 511 16TH STREET #700City: DENVER State: CO Zip: 80202**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**15 Number of Comments2 Number of Corrective Actions☒ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Fischer, Alex		alex.fischer@state.co.us	
Pohl, April	505-636-9722	apohl@enduringresources.com	SW Inspection Reports
McDaniel, James	505-444-3004	jmcdaniel@enduringresources.com	SW Inspection Reports

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
215868	WELL	PR	07/25/1993	GW	067-07473	ROYCE STATE 36-2	EI

General Comment:

On March 2, 2018 COGCC SW EPS Jim Hughes conducted an environmental field inspection of the Enduring Resources LLC Royce State #36-2. For the most recent field inspection report of this facility, please refer to document #680601415.

Location			
Lease Road:			
Type	Access		
comment:			
Corrective Action	L		Date:
Overall Good: <input checked="" type="checkbox"/>			
Signs/Marker:			
Type	TANK LABELS/PLACARDS		
Comment:	300 bbl. AST has previous operator listed.		
Corrective Action:			Date:
Type	WELLHEAD		
Comment:	Free standing sign near location entrance.		
Corrective Action:			Date:
Emergency Contact Number:			
Comment:	Posted on location signs.		
Corrective Action:			Date: _____
Good Housekeeping:			
Type	UNUSED EQUIPMENT		
Comment:	Piece of flex pipe on south side of location.		
Corrective Action:	Comply with Rule 603.f.		Date: 04/06/2018
Overall Good: <input checked="" type="checkbox"/>			
Spills:			
Type	Area	Volume	
Lube Oil		<= 1 bbl	
Comment:	Generator is leaking oil. Concrete pad and surrounding gravel are stained and wet.		
Corrective Action:	Control and contain spills/releases and clean up per Rule 906.a. Contact COGCC EPS staff.		Date: 04/06/2018
In Containment: No			
Comment:			
<input type="checkbox"/> Multiple Spills and Releases?			
Fencing/:			
Type	PUMP JACK		
Comment:	Stock panel fencing.		
Corrective Action:			Date:
Equipment:			
Type: Gas Meter Run	# 1		corrective date
Comment:			
Corrective Action:			Date:
Type: Vertical Heated Separator	# 1		
Comment:			

Corrective Action:		Date:	
Type: Deadman # & Marked	# 4		
Comment:			
Corrective Action:		Date:	
Type: Bird Protectors	# 2		
Comment:			
Corrective Action:		Date:	
Type: Pump Jack	# 1		
Comment:			
Corrective Action:		Date:	
Type: Prime Mover	# 1		
Comment:	Electric motor.		
Corrective Action:		Date:	
Type: Ancillary equipment	# 1		
Comment:	Generator. Equipment is leaking lube oil onto concrete pad and surrounding gravel.		
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS	
PRODUCED WATER	1	300 BBLs	HEATED STEEL AST		37.247756,-107.810500	
Comment:	Enclosed transfer pump within secondary containment berm.					
Corrective Action:					Date:	

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate	
Comment:					
Corrective Action:				Date:	

Venting:

Yes/No		
Comment:		
Corrective Action:		Date:

Flaring:

Type	
Comment:	
Corrective Action:	Date:

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Rip Rap	In Process			Material Handling And Spill Prevention	Pass	Drip pot on load out line.
Waddles	In Process	Compaction	Pass	Material Handling And Spill Prevention	Pass	Secondary containment for lube oil container.

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**COGCC Comments**

Comment	User	Date
On March 2, 2018 COGCC SW EPS Jim Hughes conducted an environmental field inspection of the Enduring Resources LLC Royce State #36-2. For the most recent field inspection report of this facility, please refer to document #680601415. During this inspection it was noted that the storm water BMPs along the southern edge of the location require maintenance. The generator on site is leaking lube oil onto the concrete pad and the surrounding gravel.	hughesj	03/06/2018

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
674902090	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4394882