

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

02/26/2018

Submitted Date:

02/28/2018

Document Number:

685304403**FIELD INSPECTION FORM**Loc ID 333956 Inspector Name: St John, William (Cal) On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 10133Name of Operator: HILCORP ENERGY COMPANYAddress: P O BOX 61229City: HOUSTON State: TX Zip: 77208**Status Summary:**

- ☒
- THIS IS A FOLLOW UP INSPECTION
-
- ☒
- FOLLOW UP INSPECTION REQUIRED
-
- ☐
- NO FOLLOW UP INSPECTION REQUIRED

Findings:9 Number of Comments2 Number of Corrective Actions

- ☒
- Corrective Action Response Requested

Contact Information:

Contact Name	Phone	Email	Comment
Ray, Mandi	505-324-5122	mray@hilcorp.com	
Roland, Kandis		kroland@hilcorp.com	
Trujillo, Etta		ettrujillo@hilcorp.com	
Shorty, Priscilla		pshorty@hilcorp.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
258698	WELL	PR	02/22/2007	GW	067-08373	ALLISON UNIT COM 63	PR
258699	WELL	PR	02/22/2007	GW	067-08374	ALLISON UNIT COM 138	PR

General Comment:[Inspection completed as routine follow-up inspection.](#)[This inspection does not alleviate requirement to complete any open corrective actions from previous inspections.](#)[See link at end of report for path to downloadable pictures.](#)

LocationOverall Good: ☐

Signs/Marker:			
Type	TANK LABELS/PLACARDS		
Comment:	Open top tank beside the 500 BBL tanks has no sign or labels. Corrective action completed.		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:		Date: _____
Corrective Action:		

Good Housekeeping:

Type	OTHER		
Comment:	Impacted soil outside compressor entry way. Less than 5 gallon bucket clean-up. Impacted soil and gravel noted in previous inspection were not cleaned up and properly disposed of.		
Corrective Action:	Clean-up and remediate soil to comply with Rule 906.a	Date:	03/31/2018
Type	OTHER		
Comment:	Stained soil around pump jack wellhead. Fluid released from packing. Corrective action not completed. Corrective action date remains the same to document days of noncompliance.		
Corrective Action:	Clean-up and remediate soil to comply with Rule 906.a	Date:	04/13/2017
Type	WEEDS		
Comment:	Dried thistle stalks noted in S perimeter. If not treated previously additional treatment or removal will be required to prevent infestation.		
Corrective Action:		Date:	
Type	OTHER		
Comment:	Impacted soil and gravel under separator for Allison Unit Com #63. Corrective action completed.		
Corrective Action:		Date:	
Type	UNUSED EQUIPMENT		
Comment:	Equipment removed. Corrective action completed.		
Corrective Action:		Date:	

Overall Good: ☐

Spills:				
Type	Area	Volume		

In Containment: No

Comment: ☐ Multiple Spills and Releases?

Equipment:			corrective date
Type: Deadman # & Marked	# 6		
Comment:	Located (6) marked anchors. Corrective action completed.		
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS	
PRODUCED WATER	1	OTHER	Open Top		,	
Comment:	Open top tank Allison Unit Com #63 well is steaked and rusting. Corrective action completed.					
Corrective Action:					Date:	

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)	95 BBLS.	
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficent	Base Sufficent	Adequate
Comment:				
Corrective Action:				Date:

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected FacilitiesFacility ID: 258698 Type: WELL API Number: 067-08373 Status: PR Insp. Status: PRFacility ID: 258699 Type: WELL API Number: 067-08374 Status: PR Insp. Status: PR**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401558844	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4389747
685304431	Inspection photos.	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4389737