

**FORM  
INSP**

Rev  
X/15

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

02/27/2018

Submitted Date:

02/27/2018

Document Number:

679904062

**FIELD INSPECTION FORM**

Loc ID 320981 Inspector Name: Welsh, Brian On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

OGCC Operator Number: 10626  
Name of Operator: DOVER ATWOOD CORPORATION  
Address: 1875 HARSH AVENUE SE  
City: MASSILLON State: OH Zip: 44646

**Findings:**

- 14 Number of Comments
- 0 Number of Corrective Actions
- Corrective Action Response Requested

**Contact Information:**

| Contact Name    | Phone          | Email                  | Comment                          |
|-----------------|----------------|------------------------|----------------------------------|
| Levengood, John | (330) 809-0630 | jlevengood07@gmail.com | <a href="#">BACA Inspections</a> |
| Crane, Rocky    | 719-529-0682   | rockycrane@yahoo.com   | <a href="#">Pumper (BACA)</a>    |

**Inspected Facilities:**

| Facility ID | Type | Status | Status Date | Well Class | API Num   | Facility Name        | Insp Status |
|-------------|------|--------|-------------|------------|-----------|----------------------|-------------|
| 205670      | WELL | PR     | 06/01/2017  | GW         | 009-06081 | THOMPSON-PORTER 1-10 | PR          |

**General Comment:**

[Routine Inspection](#)

| <b>Location</b>  |  |        |                 |
|--|--|--------|-----------------|
| <b>Lease Road:</b>                                     |  |        |                 |
| Type   | Access   |        |                 |
| comment:   | Short gravel road off of county road                                   |        |                 |
| Corrective Action:                                     |  |        | Date:           |
| Overall Good: <input checked="" type="checkbox"/>      |  |        |                 |
| <b>Signs/Marker:</b>                                   |  |        |                 |
| Type   | WELLHEAD   |        |                 |
| Comment:   | Lease sign mounted to meter run  |        |                 |
| Corrective Action:                                     |  |        | Date:           |
| Type   | TANK LABELS/PLACARDS   |        |                 |
| Comment:   | Sticker and stencil on water tank                                      |        |                 |
| Corrective Action:                                     |  |        | Date:           |
| Emergency Contact Number:                              |  |        |                 |
| Comment:   |  |        |                 |
| Corrective Action:                                     |  |        | Date: _____     |
| <b>Good Housekeeping:</b>                              |  |        |                 |
| Type   | STORAGE OF SUPL  |        |                 |
| Comment:   | Tubing stored next to meter run. Remove unused equipment from location |        |                 |
| Corrective Action:                                     |  |        | Date:           |
| Overall Good: <input checked="" type="checkbox"/>      |  |        |                 |
| <b>Spills:</b>   |  |        |                 |
| Type   | Area   | Volume |                 |
| In Containment: No                                     |  |        |                 |
| Comment:   |  |        |                 |
| <input type="checkbox"/> Multiple Spills and Releases? |  |        |                 |
| <b>Fencing/:</b>                                       |  |        |                 |
| Type   | PUMP JACK  |        |                 |
| Comment:   | Wire panels around unit, wellhead and compressor                       |        |                 |
| Corrective Action:                                     |  |        | Date:           |
| <b>Equipment:</b>                                      |  |        |                 |
| Type: Prime Mover                                      | # 1  |        | corrective date |
| Comment:   | Electric motor   |        |                 |
| Corrective Action:                                     |  |        | Date:           |
| Type: Vertical Separator                               | # 0  |        |                 |
| Comment:   |  |        |                 |
| Corrective Action:                                     |  |        | Date:           |
| Type: Pump Jack  | # 1  |        |                 |
| Comment:   | Churchill unit   |        |                 |

|                           |  |       |  |
|---------------------------|--|-------|--|
| Corrective Action:        |  | Date: |  |
| Type: Ancillary equipment | # 3  |       |  |
| Comment:                  | Electric panel, cathodic rectifier and phase convertor |       |  |
| Corrective Action:        |  | Date: |  |
| Type: Compressor          | # 1  |       |  |
| Comment:                  | Booster compressor next to wellhead                    |       |  |
| Corrective Action:        |  | Date: |  |
| Type: Gas Meter Run       | # 1  |       |  |
| Comment:                  |  |       |  |
| Corrective Action:        |  | Date: |  |

**Tanks and Berms:**

| Contents           | #  | Capacity | Type     | Tank ID | SE GPS                |
|--------------------|--|----------|----------|---------|-----------------------|
| PRODUCED WATER     | 1  | 200 BBLs | Open Top |         | 37.357700,-102.373830 |
| Comment:           | Fiberglass open top water tank w/Adeqaute wildlife netting |          |          |         |                       |
| Corrective Action: |  |          |          |         | Date:                 |

**Paint**

|                  |  |
|------------------|--|
| Condition        |  |
| Other (Content)  |  |
| Other (Capacity) |  |
| Other (Type)     |  |

**Berms**

| Type               | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |
|--------------------|----------|---------------------|---------------------|-------------|
| Earth              | Adequate | Walls Sufficent     | Base Sufficent      | Adequate    |
| Comment:           |          |                     |                     |             |
| Corrective Action: |          |                     |                     | Date:       |

**Venting:**

|                    |    |  |       |
|--------------------|----|--|-------|
| Yes/No             | NO |  |       |
| Comment:           |    |  |       |
| Corrective Action: |    |  | Date: |

**Flaring:**

|                    |       |
|--------------------|-------|
| Type               |       |
| Comment:           |       |
| Corrective Action: | Date: |

**Inspected Facilities**

Facility ID: 205670 Type: WELL API Number: 009-06081 Status: PR Insp. Status: PR

**Producing Well**

Comment: [Producing. Casing production. Not flowing at time of inspection](#)

Corrective Action:

Date:

**Reclamation - Storm Water - Pit**

**Storm Water:**

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| Gravel           | Pass            | Gravel                  | Pass                  |               |                          |         |

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Pits:**     NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description          | URL   |
|--------------|----------------------|---|
| 401560517    | INSPECTION SUBMITTED | <a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4391213">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4391213</a> |