

# Inspection Photos

API: 05-067-08680

Operator: BP AMERICA PRODUCTION COMPANY

Inspection Date: 3/7/2018



**Photo 1. View of the project area from the northwestern corner facing center.**



**Photo 2. View of the western portion of the project area from the northwestern corner facing southward. Revegetation is weedy with some desirable vegetation such as intermediate wheatgrass (*Thinopyron intermedium*). Surface owner equipment storage is inhibiting revegetation.**



**Photo 3. View of the northern portion of the project area from the northwestern corner facing eastward.**



**Photo 4. View of the eastern portion of the project area from the southeastern edge facing northward.**



**Photo 5. View of unknown black material within the western portion of the project area, covers an area that is approximately 50 feet long and 15 feet wide, and seeping westward off of the project area.**



**Photo 6. View of unknown black material seeping off of the western portion of the project area.**



**Photo 7. View of unknown black material release within the western interim reclamation area.**



**Photo 8. View of rig cable in the southeastern interim reclamation area. Needs to be removed along with other debris such as plastic and wire.**



**Photo 9. View of kochia debris within the production area, that needs to be removed.**