

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

03/07/2018

Submitted Date:

03/08/2018

Document Number:

691300010**FIELD INSPECTION FORM**Loc ID 318224 Inspector Name: Kraich, Adam On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**OGCC Operator Number: 46290Name of Operator: K P KAUFFMAN COMPANY INCAddress: 1675 BROADWAY, STE 2800City: DENVER State: CO Zip: 80202**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**13 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Leonard, Mike		mike.leonard@state.co.us	
, KPK		cogcc@kpk.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
240917	WELL	PR	07/01/2017	OW	123-08705	MAX SERAFINI 'B' 1	PR

**General Comment:**Unidentified 1" riser at pumping unit, see photos.

**Location**Overall Good: ☒

<b>Signs/Marker:</b>			
Type	WELLHEAD		
Comment:	Adaquate		
Corrective Action:		Date:	
Type	BATTERY		
Comment:	Adaquate		
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:	Adaquate		
Corrective Action:		Date:	

Emergency Contact Number:

Comment: Adaquate

Corrective Action:

Date: \_\_\_\_\_

Overall Good: ☒

<b>Spills:</b>			
Type	Area	Volume	

In Containment: No

Comment:

☐ Multiple Spills and Releases?

<b>Fencing/:</b>			
Type	PUMP JACK		
Comment:	4 Strand barbed wire		
Corrective Action:		Date:	

<b>Equipment:</b>			corrective date
Type: Emission Control Device	# 1		
Comment:	lit and burning		
Corrective Action:		Date:	
Type: Gas Meter Run	# 2		
Comment:			
Corrective Action:		Date:	
Type: Prime Mover	# 1		
Comment:	Electric motor		
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 1		
Comment:	Bulk separator		
Corrective Action:		Date:	
Type: Pump Jack	# 1		

Comment:	Conventional		
Corrective Action:		Date:	

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS	
CRUDE OIL	1	OTHER	STEEL AST		40.112208,-105.019397	
Comment:						
Corrective Action:						Date:

**Paint**

Condition	Adequate	
Other (Content)		
Other (Capacity)	286 BBLS	
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate	
Comment:	Shares berms with produced water pit				
Corrective Action:					Date:

**Venting:**

Yes/No			
Comment:			
Corrective Action:			
		Date:	

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

**Inspected Facilities**

Facility ID: 240917    Type: WELL    API Number: 123-08705    Status: PR    Insp. Status: PR

**Producing Well**Comment: PR

Corrective Action:

Date:

**COGCC Comments**

Comment

User

Date

Well appears to have common flowline that crosses WCR 5 to battery.

kraicha

03/08/2018

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
691300011	Inspection Photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4397568">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4397568</a>