

# Inspection Photos

API: 05-007-06206

Operator: SOUTHLAND ROYALTY COMPANY

Inspection Date: 2/28/2018



**Photo 1. View of the project area from the southwestern corner facing center.**





**Photo 2. View of the southern portion of the production area from the southwestern corner facing eastward. Revegetation grazed and largely not in identifiable condition.**





**Photo 3. View of the southern portion of the project area from the southeastern edge of the production area facing southward. Poor revegetation observed here.**





**Photo 4. View of the western portion of the project area from the southwestern corner facing northward.**





**Photo 5. View of the eastern edge of the project area from the southeastern corner facing northward. Poor revegetation on soil berm. Needs to be stabilized with vegetation.**