

Final Reclamation Inspection

March 7, 2018

Operator: CRESTONE PEAK RESOURCES OPERATING LLC- #10633

API: 05-123-12371

Inspection Document #: 682403374

Weld County, CO

SESE Section 18 T1N R68W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos

Location Name: ERIE CHAMPLIN B UNIT #2

API: 05-123-12371



Google Earth aerial imagery taken June 9, 2017, during active operations, illustrates the well location and access road used from the Erie Champlin B Unit #2. No visual evidence of equipment on location during this inspection on March 7, 2018.

Inspection Photos
Location Name: ERIE CHAMPLIN B UNIT #2
API: 05-123-12371



Photo 1. Photo taken from the facility/well location, facing East. No visual evidence of equipment on location. Well was plugged 02/2018.



Photo 2. Photo taken from the facility/well location, facing North. See comments under Photo 1.

Inspection Photos
Location Name: ERIE CHAMPLIN B UNIT #2
API: 05-123-12371



Photo 3. Photo taken from the facility/well location, facing West. See comments under Photo 1.



Photo 4. Photo taken from the facility/well location, facing South. See comments under Photo 1.

Inspection Photos
Location Name: ERIE CHAMPLIN B UNIT #2
API: 05-123-12371



Photo 5. Photo taken from the facility/well location, facing East. Photo illustrates the access road used for the location.



Photo 6. Photo taken east of the location, facing West. Photo illustrates equipment has been removed from the southeast location.