

Inspection Photos
Location Name: Thomal L Russel 'D'2
API: 05-123-08818



Pump jack site from NE view



Wellhead from NW view

Inspection Photos
Location Name: Thomal L Russel 'D'2
API: 05-123-08818



Stained soil



Leak from pump jack; view from SW