

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

02/28/2018

Submitted Date:

03/02/2018

Document Number:

682600450**FIELD INSPECTION FORM**
 Loc ID 436788 Inspector Name: Kosola, Jason On-Site Inspection ☐ 2A Doc Num: _____
Operator Information:OGCC Operator Number: 10412Name of Operator: AUSCO PETROLEUM INCAddress: 113 N SANTA FE AVENUECity: FLORENCE State: CO Zip: 81226**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:3 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Axelson, John		john.axelson@state.co.us	
Goss, Aaron	303-495-0327	agoss@fremontpetroleum.com	All Inspections
Ferrin, Jeremy		jeremy.ferrin@state.co.us	
Tim Hart		thart@fremontpetroleum.com	
Guy Goudy		ggoudy@fremontpetroleum.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
437153	WELL	TA	03/31/2016	LO	043-06226	Hudson 1	EI

General Comment:

This is an environmental inspection to document compliance with Notice of Alleged Violation (NOAV) #401263050. At the time of inspection operator has not yet submitted submitted soil samples for pit closure as required per NOAV. Operator has been informed of requirement to submit Form 27 and close pit.

At the time of issuance of this inspection the operator has begun pit closure and obtained soil samples from pit but no soil samples have been submitted to the COGCC. AS OF 2/28/2018 OPERATOR IS 381 DAYS PAST DUE ON THIS CORRECTIVE ACTION.

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: _____

Corrective Action: _____

Date: _____

Pits: ☐ NO SURFACE INDICATION OF PIT

Type:	Lined:	Pit ID:	Lat:	Long:
Reference Point: _____	Other: _____	Length: _____	Width: _____	

Lining:

Liner Type: _____

Liner Condition: _____

Comment: _____

Drilling pit remains open more than 6 months after drilling and completion activities. See attached photos.
 AS OF 2/28/2018 OPERATOR IS 381 DAYS PAST DUE ON THIS CORRECTIVE ACTION.

Corrective Action

COGCC Remediation 10815 has been approved for closure of this pit. Operator shall submit Form 27 Supplemental to the area Environmental Protection Specialist (EPS) to document closure of drilling pit. Operator shall comply with applicable COA's on permit outlining pit closure. Operator shall document disposal of pit contents, pit liner and obtain soil samples from bottom of pit to document compliance with COGCC Table 910-1. Sample results and disposal documentation shall be submitted on the Form 27 Subsequent.

Date: 02/27/2017c**Fencing:**

Fencing Type: _____

Fencing Condition: _____

Comment: _____

Corrective Action

Date: _____

Netting:

Netting Type: _____

Netting Condition: _____

Comment: _____

Corrective Action

Date: _____

Anchor Trench Present: _____

Oil Accumulation: _____

2+ feet Freeboard: _____

Comment: _____

Corrective Action

Date: _____

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401562128	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4392551
682600452	Inspection photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4392547