

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

03/09/2018

Submitted Date:

03/12/2018

Document Number:

675000237**FIELD INSPECTION FORM**

Loc ID 307125 Inspector Name: Duran, Alicia On-Site Inspection ☐ 2A Doc Num: _____

Operator Information:OGCC Operator Number: 10149Name of Operator: DEINES* JON E DBA DEINES MAZZA PARTNERSHIPAddress: 901 N COUNTY RD 21City: BERTHOUD State: CO Zip: 80513**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
☐ FOLLOW UP INSPECTION REQUIRED
☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:4 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Burn, Diana		diana.burn@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
216918	WELL	DM	11/16/2005	GW	069-06105	FAGGAN FARMS 1	DM

General Comment:

LocationOverall Good: ☒

Signs/Marker:			
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action: Date:

Overall Good: ☒

Spills:					
Type	Area	Volume			

In Containment: No

Comment: ☐ Multiple Spills and Releases?

Fencing/:			
Type	WELLHEAD		
Comment:	Panel fence		
Corrective Action:		Date:	

Venting:

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities									
Facility ID:	216918	Type:	WELL	API Number:	069-06105	Status:	DM	Insp. Status:	DM
Idle Well									
Purpose: <input type="checkbox"/> Shut In <input checked="" type="checkbox"/> Temporarily Abandoned									
Reminder: _____									
Comment: <input type="text" value="No flow line connection"/>									
Corrective Action: <input type="text"/> Date: _____									

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment:

Corrective Action:

Date:

Pits: ☐ NO SURFACE INDICATION OF PIT

Optical Gas Imaging SurveySurvey Type: RoutineCurrent Operations: ☐ Production ☐ Workover ☐ Flowback ☐ Referred to APCDGPS(entrance of location): Lat: 40.309420 Long: -105.131710Wind: Light Speed: 14 (mph) Direction From: north Weather: Partly Temperature: 59 (F)Assisting Staff Craig Carlile Camera #: _____☐ Visible Smoke ☐ Referred to CDPHE

Times Surveyed

Equipment Surveyed

Time Survey Start	AM/PM	Time Survey End	AM/PM	Equipment
11:30	AM	12:30	PM	Wellhead(s)

Comment: Well not connected to flow line.
Fencing has been installed around wellhead to prevent inadvertant valve operation by cattle accessing the well.

Corrective Action: _____ Date: _____

COGCC Comments

Comment	User	Date
<u>FLIR video conducted in response to land owner concerns regarding venting of the well. No emissions were detected.</u>	<u>durana</u>	<u>03/09/2018</u>
<u>Contacted complaintant: Shared the observation that the well did not appear to be connected to a flow line.</u> <u>Pipe fencing had been installed surrounding the well in effort to mitigate cattle contact with valve.</u>		
<u>Contact with well owner.: The owner offerd that they had a \$5,000 bond on the well and that they would be interested in learning about the orphaned well program.</u>		

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
<u>675000241</u>	<u>FLIR Video</u>	<u>http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4399900</u>