

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

03/06/2018

Submitted Date:

03/06/2018

Document Number:

679904094**FIELD INSPECTION FORM**

Loc ID 321005 Inspector Name: Welsh, Brian On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_

**Operator Information:**OGCC Operator Number: 10626Name of Operator: DOVER ATWOOD CORPORATIONAddress: 1875 HARSH AVENUE SECity: MASSILLON State: OH Zip: 44646**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**11 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

| Contact Name    | Phone          | Email                  | Comment                          |
|-----------------|----------------|------------------------|----------------------------------|
| Levengood, John | (330) 809-0630 | jlevengood07@gmail.com | <a href="#">BACA Inspections</a> |
| Crane, Rocky    | 719-529-0682   | rockycrane@yahoo.com   | <a href="#">Pumper (BACA)</a>    |

**Inspected Facilities:**

| Facility ID | Type | Status | Status Date | Well Class | API Num   | Facility Name      | Insp Status |
|-------------|------|--------|-------------|------------|-----------|--------------------|-------------|
| 205753      | WELL | PR     | 10/01/1977  | GW         | 009-06164 | THOMPSON, D R 1-25 | PR          |

**General Comment:**[Routine Inspection](#)

**Location**

|                    |                           |       |  |
|--------------------|---------------------------|-------|--|
| <b>Lease Road:</b> |                           |       |  |
| Type               | Access                    |       |  |
| comment:           | Two track through pasture |       |  |
| Corrective Action  |                           | Date: |  |

Overall Good: ☒

|                      |                                      |       |  |
|----------------------|--------------------------------------|-------|--|
| <b>Signs/Marker:</b> |                                      |       |  |
| Type                 | WELLHEAD                             |       |  |
| Comment:             | Lease sign mounted to meter run door |       |  |
| Corrective Action:   |                                      | Date: |  |

Emergency Contact Number:

Comment:

Corrective Action:

Date: \_\_\_\_\_

Overall Good: ☒

|                |      |        |  |  |  |
|----------------|------|--------|--|--|--|
| <b>Spills:</b> |      |        |  |  |  |
| Type           | Area | Volume |  |  |  |

In Containment: No

Comment:

☐ Multiple Spills and Releases?

|                    |  |       |  |
|--------------------|--|-------|--|
| <b>Fencing/:</b>   |  |       |  |
| Type               | PUMP JACK  |       |  |
| Comment:           | Wire panels around unit, wellhead and water tank |       |  |
| Corrective Action: |  | Date: |  |

|                           |                                       |       |                 |
|---------------------------|---------------------------------------|-------|-----------------|
| <b>Equipment:</b>         |                                       |       | corrective date |
| Type: Gas Meter Run       | # 1                                   |       |                 |
| Comment:                  |                                       |       |                 |
| Corrective Action:        |                                       | Date: |                 |
| Type: Ancillary equipment | # 2                                   |       |                 |
| Comment:                  | Electric panel and cathodic rectifier |       |                 |
| Corrective Action:        |                                       | Date: |                 |
| Type: Pump Jack           | # 1                                   |       |                 |
| Comment:                  | Emsco unit                            |       |                 |
| Corrective Action:        |                                       | Date: |                 |
| Type: Prime Mover         | # 1                                   |       |                 |
| Comment:                  | Electric panel                        |       |                 |
| Corrective Action:        |                                       | Date: |                 |

**Tanks and Berms:**

| Contents       | # | Capacity | Type     | Tank ID | SE GPS                |
|----------------|---|----------|----------|---------|-----------------------|
| PRODUCED WATER | 1 | 200 BBLS | Open Top |         | 37.320930,-102.315790 |

|                    |   |  |  |  |       |
|--------------------|---|--|--|--|-------|
| Comment:           | Fiberglass open top water tank w/Adequate wildlife netting.<br>Tank is empty and not in use at time of inspection |  |  |  |       |
| Corrective Action: |   |  |  |  | Date: |

**Paint**

|                  |  |  |  |  |  |
|------------------|--|--|--|--|--|
| Condition        |  |  |  |  |  |
| Other (Content)  |  |  |  |  |  |
| Other (Capacity) |  |  |  |  |  |
| Other (Type)     |  |  |  |  |  |

**Berms**

|                    |          |                     |                     |             |       |
|--------------------|----------|---------------------|---------------------|-------------|-------|
| Type               | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |       |
|                    |          |                     |                     |             |       |
| Comment:           |          |                     |                     |             |       |
| Corrective Action: |          |                     |                     |             | Date: |

**Venting:**

|                    |    |  |       |
|--------------------|----|--|-------|
| Yes/No             | NO |  |       |
| Comment:           |    |  |       |
| Corrective Action: |    |  | Date: |

**Flaring:**

|                    |  |  |       |
|--------------------|--|--|-------|
| Type               |  |  |       |
| Comment:           |  |  |       |
| Corrective Action: |  |  | Date: |

|                             |                              |                       |            |                  |
|-----------------------------|------------------------------|-----------------------|------------|------------------|
| <b>Inspected Facilities</b> |                              |                       |            |                  |
| Facility ID: 205753         | Type: WELL                   | API Number: 009-06164 | Status: PR | Insp. Status: PR |
| <b>Producing Well</b>       |                              |                       |            |                  |
| Comment:                    | Producing. Casing production |                       |            |                  |
| Corrective Action:          |                              |                       |            | Date:            |

**Reclamation - Storm Water - Pit****Storm Water:**

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| Compaction       | Pass            | Compaction              | Pass                  |               |                          |         |

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description          | URL   |
|--------------|----------------------|---|
| 401565073    | INSPECTION SUBMITTED | <a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4394982">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4394982</a> |