

Inspection Photos
Location Name: Hays 31-1H5
API: 123-11327



Wellhead



Battery/Location



Inspection Photos
Location Name: Hays 31-1H5
API: 123-11327



Produced water vault. Corrective Action: Anchor equipment ensuring anchors are engineered so the equipment will resist flotation, collapse, lateral movement, or subsidence per Rule 603.h.(2)B. Refer to the 603.h guidance document for further details.



Inspection Photos
Location Name: Hays 31-1H5
API: 123-11327



Floodplain Detail.

