

Inspection Photos

API: 05-007-06212

Operator: SOUTHLAND ROYALTY COMPANY

Inspection Date: 2/28/2018



Photo 1. View of the project area from the northeastern corner facing center.



Photo 2. View of the northern portion of the project area from the northeastern corner facing westward. Revegetation is sparse with grasses such as intermediate wheatgrass (*Thinopyron intermedium*).



Photo 3. View of the southern portion of the project area from the southeastern corner facing westward. Kochia debris needs to be removed and properly disposed of.