

Location

Overall Good:

Signs/Marker:

Type	DRILLING/RECOMP		
Comment:	Rig signage at location entrance and county road.		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action: Date: _____

Overall Good:

Spills:

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

Venting:

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities

Facility ID: 249975 Type: WELL API Number: 123-17778 Status: SI Insp. Status: PA

Cement

Cement Contractor

Contractor Name: _____ Contractor Phone: _____

Surface Casing

Cement Volume (sx): _____ Circulate to Surface: _____
 Cement Fall Back: _____ Top Job, 1" Volume: _____

Intermediate Casing

Cement Volume (sxs): _____ Good Return During Job: _____

Production Casing

Cement Volume (sx): _____ Good Return During Job: _____

Plugging Operations

Depth Plugs(feet range): 7113 - 6374 Cement Volume (sx): Cement

Good Return During Job: YES Cement Type: _____

Comment: Nio coverage previously pumped: 25 sacks
Crew on location circulating well at time of inspection.

Corrective Action: _____ Date: _____

Workover

Comment: Eastern Rig 22

Corrective Action: _____ Date: _____

COGCC Comments

Comment	User	Date
Well in process of PA. Battery remains serving API 05-123-17777, Berm SE corner at 40.24778, -104.91331	carlilec	03/15/2018

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
690001234	Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4404615