


Investment Equipment

WELLBORE DIAGRAM Before P&A

Well / Battery Gas Farm 1-17	Prospect Name	Total Depth 1,834	Est. Start Date ASAP
Location SWNE	Sec-Twn-Rng Sec 17 - 33S - 43W	Producing Horizon Red Cave	County & State Baca

WELLBORE DIAGRAM

Cementing Information



Surface Casing

8 5/8" 24# set at 839' TOC at surface

Long String

TOC for 4 1/2" at 1,050' from CBL

Tubing @ 1,500'

Perfs at 1,598' - 1,616'

Production Casing

4 1/2" 10.5# at 1,834'

Investment Equipment


WELLBORE DIAGRAM After P&A

Well / Battery Gas Farm 1-17	Prospect Name	Total Depth 1,834	Est. Start Date ASAP
Location SWNE	Sec-Twn-Rng Sec 17 - 33S - 43W	Producing Horizon Red Cave	County & State Baca

WELLBORE DIAGRAM

Surface Casing

8 5/8" 24# set at 839' TOC at surface



Use 1" tubing to spot 20 sxs of cement in the casing from 50' up.

Spot 40 sxs thru the perms, leave 100' | in the 4 1/2" casing. 40 sxs is 128' in the 8 5/8". TOC calculates 772'

Perf at 900'

Long String

TOC for 4 1/2" at 1,050' from CBL

Tubing @ 1,500'

CIBP at 1,550' plus 2 sxs

Perfs at 1,598' - 1,616'

Production Casing

4 1/2" 10.5# at 1,834'