

Inspection Photos

API: 05-007-06221

Operator: BP AMERICA PRODUCTION COMPANY

Inspection Date: 2/28/2018



Photo 1. View of the project area from the southeastern corner facing center.



Photo 2. View of the eastern portion of the project area from the southeastern corner facing northward. Revegetation is sparse and appears grazed.



Photo 3. View of the southern portion of the project area from the southeastern corner facing westward.



Photo 4. View of debris in silt northeastern silt trap. Needs to be removed and properly disposed of.



Photo 5. View of the northern portion of the project area from the northeastern corner facing westward.



Photo 6. View of musk thistles (*Carduus nutans*) scattered throughout the interim reclamation area need to be controlled.