

Inspection Photos
Location Name: Schmitt #3-36
API: 05-067-06775



2 – 300 bbl. ASTs labeled crude oil at tank battery. Note stained soil below load out valves



Stained soil below load out valve on eastern tank. Animal burrow in secondary containment berm.

Inspection Photos
Location Name: Schmitt #3-36
API: 05-067-06775



Animal burrow in secondary containment berm. Capacity of secondary containment does not appear to be adequate.



Stained soil below tank valves.

Inspection Photos
Location Name: Schmitt #3-36
API: 05-067-06775



Soil below valve on western tank has been excavated.



Schmitt #3-36 pump jack and well head.

Inspection Photos
Location Name: Schmitt #3-36
API: 05-067-06775



**Southern drop out tank with evidence of recent dirt work.
Dirt work leading to the west has recently been performed.**



Well head is wet and surrounding area is stained.

Inspection Photos
Location Name: Schmitt #3-36
API: 05-067-06775



Schmitt #3-36 location photo. No surface indication of pit #115434.



Fencing has been knocked down on southern side of pump jack.