

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

03/09/2018

Submitted Date:

03/12/2018

Document Number:

675000237

FIELD INSPECTION FORM

Loc ID 307125 Inspector Name: Duran, Alicia On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 10149
Name of Operator: DEINES* JON E DBA DEINES MAZZA PARTNERSHIP
Address: 901 N COUNTY RD 21
City: BERTHOUD State: CO Zip: 80513

Findings:

- 4 Number of Comments
- 0 Number of Corrective Actions
- Corrective Action Response Requested

Contact Information:

Contact Name	Phone	Email	Comment
Burn, Diana		diana.burn@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
216918	WELL	DM	11/16/2005	GW	069-06105	FAGGAN FARMS 1	DM

General Comment:

Location

Overall Good:

Signs/Marker:

Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action: Date: _____

Overall Good:

Spills:

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:

Type	WELLHEAD		
Comment:	Panel fence		
Corrective Action:		Date:	

Venting:

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities

Facility ID: 216918 Type: WELL API Number: 069-06105 Status: DM Insp. Status: DM

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: _____

Comment:

Corrective Action:

Date: _____

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Optical Gas Imaging Survey

Survey Type: Routine

Current Operations: Production Workover Flowback Referred to APCD

GPS(entrance of location): Lat: 40.309420 Long: -105.131710

Wind: Light Speed: 14 (mph) Direction From: north Weather: Partly Temperature: 59 (F)

Assisting Staff: Craig Carlile Camera #: _____

Visible Smoke Referred to CDPHE

Times Surveyed _____ Equipment Surveyed _____

Time Survey Start	AM/PM	Time Survey End	AM/PM	Equipment
11:30	AM	12:30	PM	Wellhead(s)

Comment: Well not connected to flow line. Fencing has been installed around wellhead to prevent inadvertant valve operation by cattle accessing the well.

Corrective Action: _____ Date: _____

COGCC Comments

Comment	User	Date
<u>FLIR video conducted in response to land owner concerns regarding venting of the well. No emissions were detected.</u>	<u>durana</u>	<u>03/09/2018</u>
<u>Contacted complainant: Shared the observation that the well did not appear to be connected to a flow line. Pipe fencing had been installed surrounding the well in effort to mitigate cattle contact with valve.</u>		
<u>Contact with well owner.: The owner offerd that they had a \$5,000 bond on the well and that they would be interested in learning about the orphaned well program.</u>		

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
<u>401571716</u>	<u>INSPECTION SUBMITTED</u>	<u>http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4399903</u>
<u>675000241</u>	<u>FLIR Video</u>	<u>http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4399900</u>