

Inspection Photos

API: 05-007-09914

Operator: CATAMOUNT ENERGY PARTNERS LLC

Inspection Date: 2/28/2018



Photo 1. View of the project area from the southeastern corner facing center.



Photo 2. View of the eastern portion of the project area from the southeastern corner facing northward. Revegetation on bermed areas is poor and does not appear to be progressing.



Photo 3. View of the southern portion of the project area from the southeastern corner facing westward. Poor revegetation in bermed areas. Approximately 100 musk thistles (*Carduus nutans*) observed.



Photo 4. View of Canada thistles (*Cirsium arvense*) within the southern portion of the project area.



Photo 5. View of silt trap in the southern portion of the project area, appears to be functioning.



Photo 6. View of Russian knapweed (*Acroptilon repens*) infestation adjacent to the northeastern portion of the project area.