

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

03/19/2018

Submitted Date:

03/19/2018

Document Number:

684905103**FIELD INSPECTION FORM**Loc ID 423916 Inspector Name: Pesicka, Conor On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 10671Name of Operator: EDGE ENERGY II LLCAddress: 621 17TH STREET SUITE 1401City: DENVER State: CO Zip: 80293**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:14 Number of Comments2 Number of Corrective Actions☒ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Leonard, Mike		mike.leonard@state.co.us	
Turner, Ben		bturner@edgeenergy1.com	Engineer; all inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
423923	WELL	PR	11/29/2012	OW	123-33796	OWL CREEK 8-64-6 1H	PR

General Comment:[Followup inspection to inspection doc#684904942](#)

Location

Overall Good: ☒

Signs/Marker:			
Type	BATTERY		
Comment:			
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Wellhead sign has been updated to reflect current operator		
Corrective Action:		Date:	
Type	CONTAINERS		
Comment:	Propane tank is labeled		
Corrective Action:		Date:	

Emergency Contact Number:

Comment: Wellhead sign has emergency contact number for prior operator

Corrective Action: Install sign to comply with rule 210.e.

Date: 03/02/2018

Good Housekeeping:

Type	OTHER		
Comment:	Stained soil at wellhead, N side of pumpjack		
Corrective Action:	Comply with rule 603.f.	Date:	04/19/2018
Type	UNUSED EQUIPMENT		
Comment:	Unused equipment has been removed		
Corrective Action:		Date:	

Overall Good: ☐

Spills:			
Type	Area	Volume	

In Containment: No

Comment: ☐ Multiple Spills and Releases?

Fencing/:

Type	LOCATION		
Comment:	barbed wire		
Corrective Action:		Date:	

Equipment:

Type: Gas Meter Run	# 1		corrective date
Comment:			
Corrective Action:		Date:	

Type: Vertical Heater Treater	# 1		
Comment:			
Corrective Action:			Date:
Type: Ancillary equipment	# 1		
Comment:	containers- 1 propane		
Corrective Action:			Date:
Type: Bird Protectors	# 3		
Comment:			
Corrective Action:			Date:
Type: Pump Jack	#		
Comment:			
Corrective Action:			Date:
Type: Prime Mover	# 1		
Comment:	gas engine		
Corrective Action:			Date:
Type: Emission Control Device	# 2		
Comment:			
Corrective Action:			Date:
Type: Ancillary equipment	# 1		
Comment:	solar & telemetry		
Corrective Action:			Date:
Type: Vertical Separator	# 1		
Comment:			
Corrective Action:			Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	2	400 BBLS	FIBERGLASS AST		40.416520,-104.359450
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Comment:	Shared with crude oil				
Corrective Action:				Date:	
Contents	#	Capacity	Type	Tank ID	SE GPS

CRUDE OIL	4	400 BBLs	STEEL AST		40.416520,-104.359450	
Comment:						
Corrective Action:						Date:
Paint						
Condition	Adequate					
Other (Content)						
Other (Capacity)						
Other (Type)						
Berms						
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance		
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate		
Comment:						
Corrective Action:						Date:
Venting:						
Yes/No	NO					
Comment:						
Corrective Action:						Date:
Flaring:						
Type						
Comment:						
Corrective Action:						Date:

Inspected Facilities									
Facility ID:	423923	Type:	WELL	API Number:	123-33796	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:		PR intermittently.							
Corrective Action:								Date:	
BradenHead									
Comment:		Bradenhead plumbed to surface.							
Corrective Action:								Date:	

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Berms	Pass					
Gravel	Pass	Gravel	Pass			

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
684905104	Site photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4407286