

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

03/20/2018

Submitted Date:

03/20/2018

Document Number:

688500024**FIELD INSPECTION FORM**Loc ID 319709 Inspector Name: CANFIELD, CHRIS On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**OGCC Operator Number: 10454Name of Operator: PETROSHARE CORPORATIONAddress: 9635 MAROON CIRCLE #400City: ENGLEWOOD State: CO Zip: 80112**Status Summary:**

- ☒
- THIS IS A FOLLOW UP INSPECTION
- 
- ☒
- FOLLOW UP INSPECTION REQUIRED
- 
- ☐
- NO FOLLOW UP INSPECTION REQUIRED

**Findings:**11 Number of Comments5 Number of Corrective Actions

- ☒
- Corrective Action Response Requested

**Contact Information:**

Contact Name	Phone	Email	Comment
Axelson, John		john.axelson@state.co.us	
Brown, Devin	(303)-349-0302	dbrown@petrosharecorp.com	Production Ops Manager
Powell, Harold	(918)-774-3120	hpowell@petrosharecorp.com	Field Ops Manager
MacLaren, Joe		joe.maclaren@state.co.us	
Deranleau, Greg		greg.deranleau@state.co.us	
Lloyd, Bill		blloyd@petrosharecorp.com	Operations Manager

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
319709	LOCATION	AC			-	STATE OF COLORADO AB-62S66W 16NESE	EI

**General Comment:**Multiple spoil piles without storm water BMPs.  
No signs, no emergency contact info was posted.

**Location**Overall Good: ☐**Signs/Marker:**

Type	WELLHEAD		
Comment:	Wellhead sign not posted as required by Rule 210.b.		
Corrective Action:	Post sign as required by Rule 210.b.	Date:	04/13/2018

**Emergency Contact Number:**

Comment:	Emergency contact info not posted as required by Rule 210.b.		
Corrective Action:	Post emergency contact info.	Date:	04/13/2018

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Venting:**

Yes/No			
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

**Location Construction**

Location ID: 319709 CDP: \_\_\_\_\_

Comment: Operator has met the corrective action deadline established in Inspection #68850022 to submit a Form 2A Oil &amp; Gas Location Assessment for prior approval as required by Rule 303.b.

Corrective Action: Operator must submit a Form 2A. The subject tank battery must not be put back into service until a Form 2A has been approved.

Date: 03/12/2018

**Form 2A COAs:**

Comment:

Corrective Action:

Date:

**Wildlife BMPs:**

Comment:

Corrective Action:

Date:

Comment: Multiple spoil piles without appropriate storm water BMPs.

Corrective Action: Install storm water BMPs as required by Rule 1002.f.

Date: 03/27/2018

**On Site Inspection (305):**Surface Owner Contact Information:

Name: \_\_\_\_\_

Address: \_\_\_\_\_

Phone Number: \_\_\_\_\_

Cell Phone: \_\_\_\_\_

Operator Rep. Contact Information:

Landman Name: \_\_\_\_\_

Phone Number: \_\_\_\_\_

Date Onsite Request Received: \_\_\_\_\_

Date of Rule 306 Consultation: \_\_\_\_\_

Request LGD Attendance: \_\_\_\_\_

LGD Contact Information:

Name: \_\_\_\_\_ Phone Number: \_\_\_\_\_ Agreed to Attend: \_\_\_\_\_

Summary of Landowner Issues:

Summary of Operator Response to Landowner Issues:

Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:

Inspected Facilities									
Facility ID:	319709	Type:	LOCATION	API Number:	-	Status:	AC	Insp. Status:	EI

--

**Environmental****Spills/Releases:**

Type of Spill: \_\_\_\_\_ Estimated Spill Volume: \_\_\_\_\_

Comment: Operator has not submitted a Form 19 Supplemental Report as required by Rule 906.b.(1) for Spill/Release Point 453361.

Corrective Action: Submit both a Form 27 Site Investigation &amp; Remediation Work Plan and a Form 19 Supplemental Report for Spill/Release Point 453361. Both submittals were identified as corrective actions in Inspection #688500022.

Date: 03/12/2018

Reportable: \_\_\_\_\_ GPS: Lat \_\_\_\_\_ Long \_\_\_\_\_

Proximity to Surface Water: \_\_\_\_\_ Depth to Ground Water: \_\_\_\_\_

**Water Well Complaint:**

Lat \_\_\_\_\_ Long \_\_\_\_\_

DWR Receipt Num: \_\_\_\_\_ Owner Name: \_\_\_\_\_ GPS : \_\_\_\_\_

**Field Parameters:**

Sample Location: \_\_\_\_\_ Comment: \_\_\_\_\_

**Spill/Remediation:**

Comment: Operator removed a partially-buried produced water vessel without prior approval of a Form 27 as required by Rule 905.b.

Corrective Action: Inspection #688500022 required as a corrective action submittal of the above-mentioned Form 27 by 03/12/2018.

Date: 03/12/2018

Emission Control Burner (ECB): \_\_\_\_\_

Comment: \_\_\_\_\_

Pilot: \_\_\_\_\_ Wildlife Protection Devices (fired vessels): \_\_\_\_\_

**COGCC Comments**

Comment	User	Date
Signs and emergency contact info are not posted. Multiple spoil piles without appropriate storm water BMPs.	canfielc	03/20/2018

**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
688500025	Photo Log	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4408509">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4408509</a>