

Inspection Photos
Location Name: Hodges Pool Unit #1
API: 05-067-05539



Meridian Hodges Pool Unit #1 location photo.



Cathodic protection well releasing gas and water.

Inspection Photos
Location Name: Hodges Pool Unit #1
API: 05-067-05539



Majority of location has been impacted by ongoing release.



Fluids and gas venting from PVC pipe.

Inspection Photos
Location Name: Hodges Pool Unit #1
API: 05-067-05539



Termination of poly line attached near well.



Debris near location entrance.

Inspection Photos
Location Name: Hodges Pool Unit #1
API: 05-067-05539



Impacted area south of location.



Wire rope, rig anchors, and other debris observed south of location.

Inspection Photos
Location Name: Hodges Pool Unit #1
API: 05-067-05539



Abandoned rig anchors observed on site.



Meridian Hodges Pool Unit #1 PA marker.

Inspection Photos
Location Name: Hodges Pool Unit #1
API: 05-067-05539



Pool of water to the north of the location. Flow path from cathodic protection well observed.



Cathodic protection well intermittently spraying water into the air.

Inspection Photos
Location Name: Hodges Pool Unit #1
API: 05-067-05539



Stream of water coming out of PVC pipe.



Location overview, PA marker located left of center in this photo.