

Inspection Photos

API: 05-067-05470

Operator: LOGOS OPERATING LLC

Inspection Date: 3/7/2018



Photo 1. View of the project area from the northwestern corner facing center.



Photo 2. View of the eastern portion of the interim reclamation area from the southeastern corner facing northward. Revegetation is comprised of big sagebrush (*Artemisia tridentata*) with cheatgrass (*Bromus tectorum*) and western wheatgrass (*Pascopyrum smithii*) understory.



Photo 3. View of erosional channels in the southeastern portion of the project area where concentrated stormwater flows have eroded the cut-slope. Stormwater controls are needed to stabilize erosion here.



Photo 4. View of the western portion of the project area from the southwestern edge of the well pad facing northward.



Photo 5. View of dead sagebrush (*Artemisia tridentata*). Sagebrush die-off appears to be the result of project activities as it is downwind of separator. Reclamation in this area may be needed.



Photo 5. Another view of sagebrush die-off west of the separator (in background).