

Inspection Photos

API: 05-067-07128

Operator: BP AMERICA PRODUCTION
COMPANY

Inspection Date: 3/7/2018



Photo 1. View of the project area from the northwestern corner facing center.



Photo 2. View of the western portion of the interim reclamation area from the northwestern corner facing westward. Revegetation is comprised of big sagebrush (*Artemisia tridentata*) with cheatgrass (*Bromus tectorum*) and western wheatgrass (*Pascopyrum smithii*) understory.



Photo 3. View of the northern portion of the project area from the northwestern corner facing eastward.



Photo 4. View of erosion in the southern portion of the project area. Appears to result from concentrated stormwater that flows off of the southern well pad.



Photo 5. View of musk thistles (*Carduus nutans*) in the southern portion of the project area. Approximately 150 individuals observed.