

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

03/22/2018

Submitted Date:

03/24/2018

Document Number:

691200029**FIELD INSPECTION FORM**
 Loc ID 302271 Inspector Name: Evins, Bret On-Site Inspection ☐ 2A Doc Num:
Operator Information:OGCC Operator Number: 100322Name of Operator: NOBLE ENERGY INCAddress: 1001 NOBLE ENERGY WAYCity: HOUSTON State: TX Zip: 77070**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:21 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Gomez, Jason		jason.gomez@state.co.us	
,		NBL_DJBU_Inspections@NB LENERGY.COM	All Inspections
Precup, Jim		james.precup@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
272714	WELL	PR		OW	123-22271	MOSSBERG 8-31	PR
297769	WELL	PR	08/14/2008	OW	123-28058	MOSSBERG J 31-27	PR

General Comment:

Location**Lease Road:**

Type	Access		
comment:	Road to Mossberg 8-31 well plowed over.		
Corrective Action	L	Date:	
Type	Main		
comment:	Adequate		
Corrective Action	L	Date:	
Type	Access		
comment:	Road to Mossberg J 31-27 well plowed over.		
Corrective Action	L	Date:	

Overall Good: ☒**Emergency Contact Number:**

Comment:		Date: _____
Corrective Action:		

Good Housekeeping:

Type	UNUSED EQUIPMENT		
Comment:	West gas meter run has been disconnected & is not in use.		
Corrective Action:		Date:	

Overall Good: ☒**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Fencing/:**

Type	SEPARATOR		
Comment:	Barbed wire fence.		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Iron panel fence (Mossberg J 31-27)		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Chain link fence (Mossberg 8-31) Observed that due to fence alignment west gate won't close.		
Corrective Action:		Date:	
Type	IGNITOR/COMBUSTOR		
Comment:	Barbed wire fence around both ECD's.		
Corrective Action:		Date:	

Equipment:				corrective date
Type: Plunger Lift	# 1			
Comment:	Mossberg J 31-27			
Corrective Action:				Date:
Type: Horizontal Heated Separator	# 1			
Comment:	Commingles 2 wells (Mossberg 8-31 & Mossberg J 31-27).			
Corrective Action:				Date:
Type: Emission Control Device	# 2			
Comment:	North 48" ECD - Tank VOC's South 48" ECD - Separator VOC's Both ECD's pilot's are not lit. ECD's appear to be in ESD mode. Separator has no pressure. GSM shows no sales for previous or current day. All production valves at wells and separator are open.			
Corrective Action:				Date:
Type: Bird Protectors	# 3			
Comment:				
Corrective Action:				Date:
Type: Plunger Lift	# 1			
Comment:	Mossberg 8-31 Casing head at well has wet fluid stain on top.			
Corrective Action:				Date:
Type: Gas Meter Run	# 2			
Comment:	West gas meter run has been disconnected & is not in use.			
Corrective Action:				Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	OTHER	PBV CONCRETE		,
Comment:	Produced water vault 3" loadline has no cap or screen to prevent avian / animal ingress.				
Corrective Action:					Date:

Paint

Condition	
Other (Content)	
Other (Capacity)	Signage shows 60 Bbls.
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate	
Comment:	Shares berms w/ produced oil tank.				
Corrective Action:				Date:	
Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	1	300 BBLs	STEEL AST		40.359565,-104.815647
Comment:					

Corrective Action:					Date:	
Paint						
Condition	Adequate					
Other (Content)						
Other (Capacity)						
Other (Type)						
Berms						
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance		
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate		
Comment: Shares berms w/ produced H2O vault.						
Corrective Action:					Date:	
Venting:						
Yes/No	NO					
Comment:						
Corrective Action:						Date:
Flaring:						
Type						
Comment:						
Corrective Action:						Date:

Inspected FacilitiesFacility ID: 272714 Type: WELL API Number: 123-22271 Status: PR Insp. Status: PR**Producing Well**

Comment: Database shows PR. Appears to be ready for producing. Separator has no pressure on it. All inlet and outlet valves for producing are open. Wellhead valves are open for producing. Gas sales showed no production for current or previous day. Please confirm status.

Corrective Action:

Date:

BradenHead

Comment: Bradenhead is plumbed to surface.

Corrective Action:

Date: _____

Facility ID: 297769 Type: WELL API Number: 123-28058 Status: PR Insp. Status: PR**Producing Well**

Comment: Database shows PR. Appears to be ready for producing. Separator has no pressure on it. All inlet and outlet valves for producing are open. Wellhead valves are open for producing. Gas sales showed no production for current or previous day. Please confirm status.

Corrective Action:

Date:

BradenHead

Comment: Bradenhead is plumbed to surface.

Corrective Action:

Date: _____

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/webblink/>) and search by document number:

Document Num	Description	URL
691200030	Site Photos	http://ogccwebblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4413006