

FORM
INSPRev
X/15

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

03/22/2018

Submitted Date:

03/26/2018

Document Number:

685304521

FIELD INSPECTION FORM

Loc ID _____ Inspector Name: _____ On-Site Inspection
326101 _____ St John, William (Cal) _____ 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
 FOLLOW UP INSPECTION REQUIRED
 NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 10663
 Name of Operator: ENDURING RESOURCES LLC
 Address: 511 16TH STREET #700
 City: DENVER State: CO Zip: 80202

Findings:

6 Number of Comments
0 Number of Corrective Actions
 Corrective Action Response Requested

Contact Information:

Contact Name	Phone	Email	Comment
McDaniel, James	505-444-3004	jmcdaniel@enduringresources.com	SW Inspection Reports
Pohl, April	505-636-9722	apohl@enduringresources.com	SW Inspection Reports
Hughes, Jim		jimo.hughes@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
215868	WELL	PR	07/25/1993	GW	067-07473	ROYCE STATE 36-2	PR

General Comment:

[Inspection completed as routine follow-up inspection resulting from corrective actions from previous inspection.](#)
[This inspection does not alleviate requirement to complete any open corrective actions from previous inspections.](#)
[See link at end of report for path to downloadable pictures.](#)

Location

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Good Housekeeping:

Type UNUSED EQUIPMENT

Comment: [Sucker rod removed corrective action completed.](#)

Corrective Action:

Date:

Overall Good:

Spills:

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

Venting:

Yes/No

Comment:

Corrective Action:

Date:

Flaring:

Type

Comment:

Corrective Action:

Date:

Inspected Facilities

Facility ID: 215868 Type: WELL API Number: 067-07473 Status: PR Insp. Status: PR

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Berms	Pass	Ditches	Pass			
Waddles	Pass	Gravel	Pass			
Check Dams	Pass					
Gravel	Pass					
Sediment Traps	Pass	Compaction	Pass	Material Handling And Spill Prevention	Pass	Lube oil tank on spill prevention.
Rip Rap	Pass					
Ditches	Pass					
Compaction	Pass					

Comment: Stormwater BMPs appear to be functioning at time of inspection. Corrective action completed.

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
685304551	Inspection pictures.	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4414287