

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

03/07/2018

Submitted Date:

03/20/2018

Document Number:

688800015**FIELD INSPECTION FORM**Loc ID 385403 Inspector Name: Hughes, Jim On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 56530Name of Operator: MERIDIAN OIL INCAddress: PO BOX 4289City: FARMINGTON State: NM Zip: 87499**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**6 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Fischer, Alex		alex.fischer@state.co.us	
Labowskie, Steve		steve.labowskie@state.co.us	
Andrews, Dave		david.andrews@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
115730	PIT				-	HODGE POOL UNIT 1	EI
214215	WELL	PA	12/21/1991	DA	067-05539	HODGES POOL UNIT 1	EI

General Comment:

On March 7, 2018 COGCC SW EPS Jim Hughes conducted an environmental field inspection of the Meridian Oil Inc. Hodges Pool Unit #1. For the most recent field inspection report of this facility, please refer to document #500147001. The purpose of this site visit was to determine the status of Pit Facility ID #115730.

Location**Lease Road:**

Type	Access		
comment:	Dirt two track.		
Corrective Action	L	Date:	

Overall Good: ☒**Signs/Marker:**

Type	OTHER		
Comment:	PA marker.		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:		Date:	
Corrective Action:		Date:	

Good Housekeeping:

Type	DEBRIS		
Comment:	Wire rope, pup joint, rig anchors and other drilling debris observed on location.		
Corrective Action:		Date:	

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: Cathodic protection well is releasing gas and water through PVC pipe.

☐ Multiple Spills and Releases?**Venting:**

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities							
Facility ID:	115730	Type:	PIT	API Number: -	Status:	Insp. Status:	EI
Facility ID:	214215	Type:	WELL	API Number: 067-05539	Status: PA	Insp. Status:	EI

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PITType: Evaporation

Lined:

Pit ID: 115730Lat: 37.160516Long: -108.171177Reference Point: Other: Length: Width: **Lining:**

Liner Type:

Liner Condition:

Comment:

Corrective Action

Date: c**Fencing:**

Fencing Type:

Fencing Condition:

Comment:

Corrective Action

Date:

Netting:

Netting Type:

Netting Condition:

Comment:

Corrective Action

Date:

Anchor Trench Present:

Oil Accumulation:

2+ feet Freeboard:

Comment:

No surface indication of pit observed during field inspection. Diagram in pit scout card indicates a 25 by 25 by 6' pit existed near the separator/dehydrator.

Corrective Action

Date:

COGCC Comments

Comment	User	Date
<p>On March 7, 2018 COGCC SW EPS Jim Hughes conducted an environmental field inspection of the Meridian Oil Inc. Hodges Pool Unit #1. For the most recent field inspection report of this facility, please refer to document #500147001. The purpose of this site visit was to determine the status of Pit Facility ID #115730.</p> <p>During this field inspection a cathodic protection well in the northwest corner of the location was observed releasing fluids from a PVC pipe. The anode cables have been cut off and the well is sitting in a pool of water. This well is now registered with the DWR. The permit number is 289680. The permit estimates the depth at 450'. The construction logs state that the well was drilled to a depth of 500'.</p> <p>An engineering brief (Document #1857797) in the COGIS database well file provides some history about this cathodic protection well.</p> <p>Pit Facility ID #115730 was not observed during this field inspection. Pit report (Document #656752) documents a 25 by 25 by 6' deep existing evaporation pit located near the separator/dehydrator.</p>	hughesj	03/20/2018

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401581065	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4408967
688800016	Inspection Photos.	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4408960