

FORM  
INSPRev  
X/15

**State of Colorado**  
**Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

03/20/2018

Submitted Date:

03/20/2018

Document Number:

688800017

**FIELD INSPECTION FORM**

Loc ID \_\_\_\_\_ Inspector Name: \_\_\_\_\_ On-Site Inspection   
325458 \_\_\_\_\_ Hughes, Jim \_\_\_\_\_ 2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION  
 FOLLOW UP INSPECTION REQUIRED  
 NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

OGCC Operator Number: \_\_\_\_\_ 10133 \_\_\_\_\_  
Name of Operator: HILCORP ENERGY COMPANY \_\_\_\_\_  
Address: P O BOX 61229 \_\_\_\_\_  
City: \_\_\_\_\_ HOUSTON \_\_\_\_\_ State: \_\_\_\_\_ TX \_\_\_\_\_ Zip: \_\_\_\_\_ 77208 \_\_\_\_\_

**Findings:**

- \_\_\_\_\_ 15 Number of Comments  
\_\_\_\_\_ 1 Number of Corrective Actions  
 Corrective Action Response Requested

**Contact Information:**

Contact Name	Phone	Email	Comment
Shorty, Priscilla		pshorty@hilcorp.com	
Ray, Mandi	505-324-5122	mray@hilcorp.com	
Fischer, Alex		alex.fischer@state.co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
364	WELL	PR		GW	067-09496	DOWLER 1B	EI
115500	PIT				-	DOWLER 1-A	EI
214802	WELL	PR	05/31/2012	GW	067-06406	DOWLER 1A	EI

**General Comment:**

On March 20, 2018 COGCC SW EPS Jim Hughes conducted an environmental field inspection of the Hilcorp Dowler #1A. For the most recent field inspection report of this facility, please refer to document #685302560. The purpose of this site visit was to determine the status of Pit Facility ID #115500. During this inspection a release was occurring at the Dowler #1B well head. The emergency contact number was used to leave a message reporting the release. A Hilcorp representative arrived on location to replace the well head packing and stop the release.

Location			
<b>Lease Road:</b>			
Type	Access		
comment:	Gravel road.		
Corrective Action:			Date:
Overall Good: <input checked="" type="checkbox"/>			
<b>Signs/Marker:</b>			
Type	CONTAINERS		
Comment:	Chemical injection system has label and placard.		
Corrective Action:			Date:
Type	WELLHEAD		
Comment:	Free standing signs near both well heads.		
Corrective Action:			Date:
Emergency Contact Number:			
Comment:	Contact number used to leave message reporting release from Dowler #1B well head. Hilcorp returned call and dispatched pumper to location.		
Corrective Action:			Date:
Overall Good: <input type="checkbox"/>			
<b>Spills:</b>			
Type	Area	Volume	
Produced Water	WELLHEAD	<= 1 bbl	
Comment:	Well head was iced up upon arrival. Gas and water could be seen and heard coming from packing on well head. Well head and surrounding area was wet.		
Corrective Action:	Control and contain spills/releases and clean up per Rule 906.a. Contact COGCC EPS staff. Remove free fluids and contact COGCC EPS staff per Rule 906.b.		Date: 03/23/2018
In Containment: No			
Comment:			
<input type="checkbox"/> Multiple Spills and Releases?			
<b>Fencing/:</b>			
Type	WELLHEAD		
Comment:	Steel pipe barricade fence around well heads.		
Corrective Action:			Date:
Type	OTHER		
Comment:	Steel pipe barricade fencing around below grade valve access.		
Corrective Action:			Date:
Type	PUMP JACK		
Comment:	Guard fencing.		
Corrective Action:			Date:
<b>Equipment:</b>			
Type:	Vertical Heated Separator	# 2	corrective date
Comment:			

Corrective Action:		Date:	
Type: Ancillary equipment	# 1		
Comment:	Telemetry equipment.		
Corrective Action:		Date:	
Type: Pig Station	# 1		
Comment:			
Corrective Action:		Date:	
Type: Prime Mover	# 1		
Comment:	Electric motor.		
Corrective Action:		Date:	
Type: Gas Meter Run	# 1		
Comment:			
Corrective Action:		Date:	
Type: Plunger Lift	# 1		
Comment:			
Corrective Action:		Date:	
Type: Other	# 1		
Comment:	Below grade valve access.		
Corrective Action:		Date:	
Type: Ancillary equipment	# 1		
Comment:	Electrical supply equipment.		
Corrective Action:		Date:	
Type: Flow Line	# 1		
Comment:			
Corrective Action:		Date:	
Type: Bird Protectors	# 1		
Comment:			
Corrective Action:		Date:	
Type: Pump Jack	# 1		
Comment:			
Corrective Action:		Date:	
Type: Deadman # & Marked	# 8		
Comment:			
Corrective Action:		Date:	

**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type			
------	--	--	--

Comment:	
Corrective Action:	Date:

**Inspected Facilities**

Facility ID: 364 Type: WELL API Number: 067-09496 Status: PR Insp. Status: EI

Facility ID: 115500 Type: PIT API Number: - Status:  Insp. Status: EI

Facility ID: 214802 Type: WELL API Number: 067-06406 Status: PR Insp. Status: EI

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Pass	Material Handling And Spill Prevention	Pass	Chemical injection system on secondary containment
Compaction	Pass	Compaction	Pass			

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Pits:**     NO SURFACE INDICATION OF PIT

**COGCC Comments**

Comment	User	Date
<p>On March 20, 2018 COGCC SW EPS Jim Hughes conducted an environmental field inspection of the Hilcorp Dowler #1A. For the most recent field inspection report of this facility, please refer to document #685302560. The purpose of this site visit was to determine the status of Pit Facility ID #115500. During this inspection a release was occurring at the Dowler #1B well head. The emergency contact number was used to leave a message reporting the release. A Hilcorp representative arrived on location to replace the well head packing and stop the release.</p> <p>No surface indication of pit facility ID #115500 was observed during this inspection. The Dowler #1B well head was wet and had ice on it upon arrival. Gas and water could be heard and seen from the well head packing. The Hilcorp representative replaced the worn out packing on the well head. The operator shall submit a Form 19 spill report within seventy two hours of discovery.</p>	hughesj	03/20/2018

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401581066	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4408968">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4408968</a>
688800018	Inspection Photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4408961">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4408961</a>