

Inspection Photos

API: 05-067-07950

Operator: LOGOS OPERATING LLC

Inspection Date: 3/7/2018



Photo 1. View of the project area from the southwestern corner facing center.



Photo 2. View of the western portion of the project area from the southwestern corner facing northward. Little to no desirable vegetation here.



Photo 3. View of the southern portion of the project area from the southwestern corner facing eastward. Little desirable vegetation observed.



Photo 4. View of drainage area where erosion is occurring in the south-central portion of the project area. Stormwater controls are needed.



Photo 5. Birdseye view of little to no revegetation within the areas not needed for production operations.



Photo 6. View of project area in the foreground with little to no vegetation, and reference area that is vegetated outside of fenced area.



Photo 7. View of approximately 100 musk thistles within the eastern portion of the project area.



Photo 8. View of the eastern portion of the project area that is largely revegetated with western wheatgrass (*Pascopyrum smithii*).