

Inspection Photos

API: 05-067-05486

Operator: LOGOS OPERATING LLC

Inspection Date: 3/7/2018



Photo 1. View of the project area from the southeastern corner working area.



Photo 2. View of the eastern edge of the project area from the southeastern corner facing northward.



Photo 3. View of the northern portion of the project area from the northwestern corner facing eastward. Large kochia (*Kochia scoparia*) debris present, and needs to be removed.



Photo 4. View of kochia debris that is broken off and stuck on northeastern fenceline.