

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

03/28/2018

Submitted Date:

03/28/2018

Document Number:

679904189**FIELD INSPECTION FORM**
 Loc ID 321140 Inspector Name: Welsh, Brian On-Site Inspection ☐ 2A Doc Num:
Operator Information:OGCC Operator Number: 10117Name of Operator: LORENTZ OIL & GAS LLCAddress: 3330 FRENCH PARK DRCity: EDMOND State: OK Zip: 73034**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:18 Number of Comments4 Number of Corrective Actions☒ Corrective Action Response Requested**Contact Information:**

| Contact Name | Phone | Email | Comment |
|----------------|------------------|---------------------------|---------|
| Walker, Mark | 405-844-3750 off | markw@coxinet.net | |
| Lorentz, Brian | 405-844-3750 off | lorentz@coxinet.net | |
| Ferrin, Jeremy | | jeremy.ferrin@state.co.us | |

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|---------------|-------------|
| 206137 | WELL | PR | 08/22/1995 | GW | 009-06553 | LIPPOLDT 1-14 | PR |

General Comment:

Routine Inspection

Location

| | | | |
|--------------------|---------------------------|-------|--|
| Lease Road: | | | |
| Type | Access | | |
| comment: | Two track through pasture | | |
| Corrective Action: | | Date: | |

Overall Good: ☒

| | | | |
|----------------------|---|-------|--|
| Signs/Marker: | | | |
| Type | WELLHEAD | | |
| Comment: | Install lease sign at wellhead or move sign at CR U to location | | |
| Corrective Action: | | Date: | |
| Type | OTHER | | |
| Comment: | Lease sign at entrance by CR U | | |
| Corrective Action: | | Date: | |
| Type | TANK LABELS/PLACARDS | | |
| Comment: | Stickers on water tank | | |
| Corrective Action: | | Date: | |

Emergency Contact Number:

| | | |
|--------------------|--|-------------|
| Comment: | | |
| Corrective Action: | | Date: _____ |

| | | | |
|---------------------------|---------------------------------------|-------|------------|
| Good Housekeeping: | | | |
| Type | WEEDS | | |
| Comment: | Weeds across location | | |
| Corrective Action: | Remove and maintain weeds on location | Date: | 02/10/2016 |
| Type | DEBRIS | | |
| Comment: | Misc debris laying around | | |
| Corrective Action: | Remove debris from location | Date: | 02/10/2016 |

Overall Good: ☐

| | | | |
|--------------------|---|----------|------------------|
| Spills: | | | |
| Type | Area | Volume | |
| Lube Oil | Valve | <= 1 bbl | |
| Comment: | Lube oil on the ground next to booster compressor | | |
| Corrective Action: | Remove stained soil around compressor and install blowdown tank | | Date: 02/10/2016 |

In Containment: No

Comment: ☐ Multiple Spills and Releases?

| | | | |
|--------------------|-----------------------------------|-------|--|
| Fencing/: | | | |
| Type | LOCATION | | |
| Comment: | Wire fence around entire location | | |
| Corrective Action: | | Date: | |

| | | | |
|--|-----|-------|-----------------|
| Equipment: | | | corrective date |
| Type: Vertical Separator | # 1 | | |
| Comment: Vertical gas separator on north side of meter run | | | |
| Corrective Action: | | Date: | |
| Type: Ancillary equipment | # 1 | | |
| Comment: Gas scrubber | | | |
| Corrective Action: | | Date: | |
| Type: Pump Jack | # 1 | | |
| Comment: Cabot unit | | | |
| Corrective Action: | | Date: | |
| Type: Gas Meter Run | # 3 | | |
| Comment: 1-Master meter run 2-Meter runs for Lippoldt 1-14 & 1-23 | | | |
| Corrective Action: | | Date: | |
| Type: Prime Mover | # 1 | | |
| Comment: Arrow gas engine | | | |
| Corrective Action: | | Date: | |
| Type: Compressor | # 1 | | |
| Comment: Booster compressor in metal shed | | | |
| Corrective Action: | | Date: | |

Tanks and Berms:

| Contents | # | Capacity | Type | Tank ID | SE GPS |
|---|---|----------|----------|---------|-----------------------|
| PRODUCED WATER | 1 | 100 BBLS | Open Top | | 37.256570,-102.336090 |
| Comment: Fiberglass open top water tank w/Adequate wildlife netting. Tank is empty at time of inspection | | | | | |
| Corrective Action: | | | | | Date: |

Paint

| | |
|------------------|--|
| Condition | |
| Other (Content) | |
| Other (Capacity) | |
| Other (Type) | |

Berms

| Type | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |
|--|----------|---------------------|---------------------|------------------|
| | | | | |
| Comment: Water leg is connected at wellhead and plumbed to water tank | | | | |
| Corrective Action: Add berms around water tank or remove from location | | | | Date: 02/10/2016 |

Venting:

| | | |
|--------------------|----|-------|
| Yes/No | NO | |
| Comment: | | |
| Corrective Action: | | Date: |

Flaring:

| | | |
|--------------------|--|-------|
| Type | | |
| Comment: | | |
| Corrective Action: | | Date: |

| Inspected Facilities | | | | | | | | | |
|----------------------|--|-------|------|-------------|-----------|---------|----|---------------|----|
| Facility ID: | 206137 | Type: | WELL | API Number: | 009-06553 | Status: | PR | Insp. Status: | PR |
| Producing Well | | | | | | | | | |
| Comment: | Producing. Casing production. Central meter run for Lippoldt 1-14 & 1-23 | | | | | | | | |
| Corrective Action: | | | | | | | | Date: | |

Reclamation - Storm Water - Pit**Storm Water:**

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| Compaction | Pass | Compaction | Pass | | | |

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|------------------------------|---|
| 679904190 | Location photos from 3/28/18 | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4416982 |