

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

03/23/2018

Submitted Date:

03/23/2018

Document Number:

689401072

FIELD INSPECTION FORM

Loc ID 334067 Inspector Name: CONKLIN, CURTIS On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 10456
Name of Operator: CAERUS PICEANCE LLC
Address: 1001 17TH STREET #1600
City: DENVER State: CO Zip: 80202

Findings:

- 8 Number of Comments
- 0 Number of Corrective Actions
- Corrective Action Response Requested

Contact Information:

| Contact Name | Phone | Email | Comment |
|------------------------|-------|---------------------------------------|--------------------------|
| Caerus Oil And Gas LLC | | COGCC.inspections@caerusoilandgas.com | All Piceance inspections |

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|-------------------|-------------|
| 287563 | WELL | PR | 08/10/2012 | GW | 077-09170 | WHITE 14-2(A14OU) | PR |
| 287564 | WELL | SI | 09/01/2017 | GW | 077-09169 | WHITE 14-8(A14OU) | SI |
| 287565 | WELL | PR | 07/12/2012 | GW | 077-09168 | WHITE 13-4(A14OU) | PR |

General Comment:

This is a follow up inspection to FIR Doc#689401002 in response to FIRR Doc#401581052. Any corrective actions not addressed from previous inspections are still applicable.

Location

Overall Good:

| | | | |
|----------------------|----------------------|--|-------|
| Signs/Marker: | | | |
| Type | WELLHEAD | | |
| Comment: | | | |
| Corrective Action: | | | Date: |
| Type | TANK LABELS/PLACARDS | | |
| Comment: | | | |
| Corrective Action: | | | Date: |

| | |
|---------------------------|--|
| Emergency Contact Number: | |
| Comment: | Posted Emergency Contact Number 1-970-285-2615 |
| Corrective Action: | Date: _____ |

Overall Good:

| | | | |
|----------------|------|--------|--|
| Spills: | | | |
| Type | Area | Volume | |

In Containment: No
 Comment: _____
 Multiple Spills and Releases?

| | | | |
|--------------------|------------|--|-------|
| Fencing/: | | | |
| Type | LOCATION | | |
| Comment: | Wire fence | | |
| Corrective Action: | | | Date: |

Tanks and Berms:

| Contents | # | Capacity | Type | Tank ID | SE GPS |
|--------------------|---|----------|-----------|---------|--------|
| CONDENSATE | 1 | 300 BBLS | STEEL AST | | , |
| Comment: | | | | | |
| Corrective Action: | | | | | Date: |

| | |
|------------------|----------|
| Paint | |
| Condition | Adequate |
| Other (Content) | |
| Other (Capacity) | |
| Other (Type) | |

| Berms | | | | |
|--------------------|----------|---------------------|---------------------|-------------|
| Type | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |
| Metal | Adequate | Walls Sufficient | Base Sufficient | Adequate |
| Comment: | | | | |
| Corrective Action: | | | | Date: |

| Contents | # | Capacity | Type | Tank ID | SE GPS |
|------------|---|----------|------------------|---------|--------|
| CONDENSATE | 1 | 300 BBLS | HEATED STEEL AST | | , |

| | | |
|--------------------|--|-------|
| Comment: | | |
| Corrective Action: | | Date: |

Paint

| | | |
|------------------|----------|--|
| Condition | Adequate | |
| Other (Content) | | |
| Other (Capacity) | | |
| Other (Type) | | |

Berms

| Type | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |
|--------------------|---|---------------------|---------------------|-------------|
| Metal | Adequate | Walls Sufficient | Base Sufficient | Adequate |
| Comment: | Tank containment has been repaired. FIRR Doc#401581052 submitted and approved. Corrective action from previous inspection has been met. | | | |
| Corrective Action: | | | | Date: |

Venting:

| | | | |
|--------------------|----|--|-------|
| Yes/No | NO | | |
| Comment: | | | |
| Corrective Action: | | | Date: |

Flaring:

| | | |
|--------------------|--|-------|
| Type | | |
| Comment: | | |
| Corrective Action: | | Date: |

Inspected Facilities

Facility ID: 287563 Type: WELL API Number: 077-09170 Status: PR Insp. Status: PR

Producing Well

Comment: PR w/ Plunger

Corrective Action:

Date:

Facility ID: 287564 Type: WELL API Number: 077-09169 Status: SI Insp. Status: SI

Idle Well

Purpose: Shut In Temporarily Abandoned

Reminder: _____

Comment: Well last produced for 2 days in August 2017.

Corrective Action:

Date: _____

Facility ID: 287565 Type: WELL API Number: 077-09168 Status: PR Insp. Status: PR

Producing Well

Comment: PR w/ Plunger

Corrective Action:

Date:

Reclamation - Storm Water - Pit

Storm Water:

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| Berms | Pass | Compaction | Pass | | | |
| Compaction | Pass | Gravel | Pass | | | |
| Gravel | Pass | | | | | |

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|--------------------------|---|
| 401584639 | INSPECTION SUBMITTED | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4411918 |
| 689401073 | A 14 OU Follow Up Photos | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4411908 |