

**Inspection Photos**  
**Location Name: Rudnik #33-27 (Tank Battery)**  
**API: 05-121-08687**  
**Inspection Date: March 22, 2018**



**Photo #1 – Crude oil tank battery, looking west. Note eroded berms, lack of content labels, and damaged/faded NFPA placards.**



**Photo #2 – Shallow earthen berms and oil-stained soil remaining between 300 bbl crude oil ASTs. Note west steel AST lacks content label and has conflicting NFPA placards (left side).**

## Inspection Photos

Location Name: Rudnik #33-27 (Tank Battery)

API: 05-121-08687

Inspection Date: March 22, 2018



**Photo #3 – Produced water steel ASTs. Note shallow earthen berms.**

