

Inspection Photos

Location Name: Pierce Unit #2 API: 05-123-07596

Inspection Date: 3/30/2018



Photo 1 – Well sign at County Road



Photo 2 – Excavation at release area, looking west. Pipeline on right is apparently abandoned line from the plugged Priddy #1



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

Location Name: Pierce Unit #2 API: 05-123-07596

Inspection Date: 3/30/2018



Photo 3 – Excavation at release looking south. Release was apparent at/near elbow in flowline.



Photo 4 – Excavation at release looking north.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

Location Name: Pierce Unit #2 API: 05-123-07596

Inspection Date: 3/30/2018



Photo 5 – Excavation at release looking approximately east-southeast. Impacted material remains in excavation.



Photo 6 – Photo of the plugged Priddy #1 marker looking east toward excavation on flowline for Pierce Unit #2.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources