

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

03/22/2018

Submitted Date:

03/26/2018

Document Number:

685304521**FIELD INSPECTION FORM**
 Loc ID 326101 Inspector Name: St John, William (Cal) On-Site Inspection ☐ 2A Doc Num:                     
**Operator Information:**OGCC Operator Number: 10663Name of Operator: ENDURING RESOURCES LLCAddress: 511 16TH STREET #700City: DENVER State: CO Zip: 80202**Status Summary:**

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**6 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
McDaniel, James	505-444-3004	jmcdaniel@enduringresources.com	<a href="#">SW Inspection Reports</a>
Pohl, April	505-636-9722	apohl@enduringresources.com	<a href="#">SW Inspection Reports</a>
Hughes, Jim		jimo.hughes@state.co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
215868	WELL	PR	07/25/1993	GW	067-07473	ROYCE STATE 36-2	PR

**General Comment:**

[Inspection completed as routine follow-up inspection resulting from corrective actions from previous inspection.](#)

[This inspection does not alleviate requirement to complete any open corrective actions from previous inspections.](#)

[See link at end of report for path to downloadable pictures.](#)

**Location**Overall Good: ☐

Emergency Contact Number:

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Good Housekeeping:**

Type

UNUSED EQUIPMENT

Comment:

Sucker rod removed corrective action completed.

Corrective Action:

Date:

Overall Good: ☐**Spills:**

Type

Area

Volume

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Venting:**

Yes/No

Comment:

Corrective Action:

Date:

**Flaring:**

Type

Comment:

Corrective Action:

Date:

Inspected Facilities									
Facility ID:	215868	Type:	WELL	API Number:	067-07473	Status:	PR	Insp. Status:	PR

--

**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Berms	Pass	Ditches	Pass			
Rip Rap	Pass					
Ditches	Pass					
Compaction	Pass					
Sediment Traps	Pass	Compaction	Pass	Material Handling And Spill Prevention	Pass	Lube oil tank on spill prevention.
Gravel	Pass					
Check Dams	Pass					
Waddles	Pass	Gravel	Pass			

Comment: [Stormwater BMPs appear to be functioning at time of inspection. Corrective action completed.](#)

Corrective Action:

Date: \_\_\_\_\_

**Pits:** ☒ NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401587379	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4414304">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4414304</a>
685304551	Inspection pictures.	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4414287">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4414287</a>