

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

04/03/2018

Submitted Date:

04/03/2018

Document Number:

684905220**FIELD INSPECTION FORM**

Loc ID \_\_\_\_\_ Inspector Name: \_\_\_\_\_ On-Site Inspection ☐  
 310706 \_\_\_\_\_ Pesicka, Conor \_\_\_\_\_ 2A Doc Num: \_\_\_\_\_

**Operator Information:**OGCC Operator Number: 10575Name of Operator: 8 NORTH LLCAddress: 370 17TH STREET SUITE 5300City: DENVER State: CO Zip: 80202**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION  
☐ FOLLOW UP INSPECTION REQUIRED  
☒ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**6 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**Contact Information:**

| Contact Name | Phone | Email                                 | Comment                                   |
|--------------|-------|---------------------------------------|-------------------------------------------|
| ,            |       | COGCCInspections@extracti<br>onog.com | All Inspections inc 8 North, 7 North, XPR |

**Inspected Facilities:**

| Facility ID | Type | Status | Status Date | Well Class | API Num   | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|---------------|-------------|
| 296651      | WELL | SI     | 06/01/2017  | GW         | 123-26842 | WELD 11-28    | TA          |

**General Comment:**

**Location**Overall Good: ☒

|                      |          |       |  |
|----------------------|----------|-------|--|
| <b>Signs/Marker:</b> |          |       |  |
| Type                 | WELLHEAD |       |  |
| Comment:             |          |       |  |
| Corrective Action:   |          | Date: |  |

Emergency Contact Number:

Comment:

Corrective Action:  Date:

Overall Good: ☒

|                |      |        |  |  |  |
|----------------|------|--------|--|--|--|
| <b>Spills:</b> |      |        |  |  |  |
| Type           | Area | Volume |  |  |  |

In Containment: No

Comment: ☐ Multiple Spills and Releases?

|                    |              |       |  |
|--------------------|--------------|-------|--|
| <b>Fencing/:</b>   |              |       |  |
| Type               | PUMP JACK    |       |  |
| Comment:           | cattle panel |       |  |
| Corrective Action: |              | Date: |  |

|                    |            |       |                 |
|--------------------|------------|-------|-----------------|
| <b>Equipment:</b>  |            |       | corrective date |
| Type: Pump Jack    | # 1        |       |                 |
| Comment:           |            |       |                 |
| Corrective Action: |            | Date: |                 |
| Type: Prime Mover  | # 1        |       |                 |
| Comment:           | gas engine |       |                 |
| Corrective Action: |            | Date: |                 |

**Tanks and Berms:**

|                    |                       |          |                     |         |        |  |
|--------------------|-----------------------|----------|---------------------|---------|--------|--|
| Contents           | #                     | Capacity | Type                | Tank ID | SE GPS |  |
|                    |                       |          | CENTRALIZED BATTERY |         | ,      |  |
| Comment:           | refer to locid#306282 |          |                     |         |        |  |
| Corrective Action: |                       |          |                     |         | Date:  |  |

**Paint**

|                  |  |  |
|------------------|--|--|
| Condition        |  |  |
| Other (Content)  |  |  |
| Other (Capacity) |  |  |
| Other (Type)     |  |  |

**Berms**

|      |          |                     |                     |             |
|------|----------|---------------------|---------------------|-------------|
| Type | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |
|      |          |                     |                     |             |



**Inspected Facilities**Facility ID: 296651 Type: WELL API Number: 123-26842 Status: SI Insp. Status: TA**Idle Well**Purpose: ☐ Shut In ☒ Temporarily Abandoned Reminder: EQUIPMENT PRESENT/DISCONNECTEDComment: TA. Last produced May 2017. No current MIT on record or delinquent as required by Rule 326Corrective Action: Contact dnr\_cogccengineering@state.co.us with resolution plan.Date: 04/13/2018**BradenHead**Comment: Bradenhead plumbed to surface.Corrective Action:Date:

**Reclamation - Storm Water - Pit****Storm Water:**

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| Gravel           | Pass            | Gravel                  | Pass                  |               |                          |         |

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL                                                                                                                                                                 |
|--------------|-------------|---------------------------------------------------------------------------------------------------------------------------------------------------------------------|
| 684905221    | Site photos | <a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4423514">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4423514</a> |