

Inspection Photos

Loc# 433573

Operator: Caerus

Inspection Number: 680102819

Inspection Date: 3/29/2018



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources



Photo#1:
Overview of Location from main road to Southeast.

March 29, 2018



Photo#2:
Looking West along South Location Berm.

March 29, 2018



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Caerus Loc# 433573



Photo#3:

Looking South along Location East Perimeter Berm.

March 29, 2018



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Caerus Loc# 433573



Photo#3:

Wattles should be monitored as it appears they may have been installed at previous start date of Construction Notice in 2013.

March 29, 2018

Photo#4:



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Caerus Loc# 433573



Photo#5:

Photo#6:

There is a Lack of BMPs on Access road Cut & Fill Slope sides & ditches.

March 29, 2018



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Caerus Loc# 433573



Photo#7:

Sediment & materials migration was noted from top of pad (flat staging/dump Point indicated by arrow) to Southwest corner of Pad.

March 29, 2018



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Caerus Loc# 433573



Photo#8:

Sediment & materials migration was noted from top of pad (flat staging/dump Point, indicated by arrow) to Southwest corner of Pad.

March 29, 2018



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Caerus Loc# 433573