

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

03/29/2018

Submitted Date:

03/30/2018

Document Number:

687901551**FIELD INSPECTION FORM**Loc ID 308959 Inspector Name: DURAN, JOHN On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**OGCC Operator Number: 10084Name of Operator: PIONEER NATURAL RESOURCES USA INCAddress: 5205 N O'CONNOR BLVD STE 200City: IRVING State: TX Zip: 75039**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**11 Number of Comments5 Number of Corrective Actions☒ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Distribution, Pioneer	972-444-9001	COGCC.Inspections@pxd.com	<a href="#">All Inspections</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
285662	WELL	TA	09/01/2017	GW	071-08867	LAST CHANCE 31-17	TA

**General Comment:**

## Location

**Lease Road:**

Type	Access		
comment:	Access road has deep ruts.		
Corrective Action	Need to fix ruts in road.	Date:	04/30/2018

Overall Good: ☐**Signs/Marker:**

Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

**Emergency Contact Number:**

Comment:		Date:	
Corrective Action:		Date:	

Overall Good: ☒**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Fencing/:**

Type	PIT		
Comment:	Liner has holes.		
Corrective Action:	Need to fix or replace liner or close pit.	Date:	04/30/2018

**Equipment:**

Type: Vertical Separator	# 1		corrective date
Comment:			
Corrective Action:		Date:	
Type: Deadman # & Marked	# 4		
Comment:			
Corrective Action:		Date:	
Type: Ancillary equipment	# 2		
Comment:	2 risers with no plugs, locks or Lock out tags.		
Corrective Action:	Put locks or plug with Lock out tags.	Date:	04/30/2018
Type: Ancillary equipment	# 1		
Comment:	Wellhead		
Corrective Action:		Date:	
Type: Gas Meter Run	# 1		
Comment:			
Corrective Action:		Date:	



Inspected Facilities									
Facility ID:	285662	Type:	WELL	API Number:	071-08867	Status:	TA	Insp. Status:	TA
Idle Well									
Purpose: <input type="checkbox"/> Shut In <input checked="" type="checkbox"/> Temporarily Abandoned Reminder: _____									
Comment: <div>Production Records : May 2015. Shut In : Aug. 2017. TA : Sept. 2017. No MiT Records found.</div>									
Corrective Action: <div></div> Date: _____									

**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Fail			

Comment: Ruts on access road.Corrective Action: Ruts in access road and BMP maintenance need to be addressed.Date: 04/30/2018**Pits:** ☐ NO SURFACE INDICATION OF PITType: Produced Water Lined: YES Pit ID: Lat: Long:

Reference Point: Other: Length: Width:

**Lining:**Liner Type: Plastic Liner Condition: InadequateComment: Holes in liner.Corrective Action: Liner needs to be fixed or replaced or pit closed.Date: 04/30/2018c**Fencing:**Fencing Type: Livestock Fencing Condition: Adequate

Comment:

Corrective Action:

Date:

**Netting:**

Netting Type: Netting Condition:

Comment:

Corrective Action:

Date:

Anchor Trench Present: Oil Accumulation: NO 2+ feet Freeboard: YESComment: 30' x 70'

Corrective Action:

Date:

Monitoring:

Monitoring Type

Comment`

Chain

Yellow

**COGCC Comments**

Comment	User	Date
<u>SEE : Equipment : 2 Risers, SEE : Lease Roads : Access, SEE : Pits : Liner. Production Records : May 2015. Shut In : Aug.2017. Temp. Abandon : Sept 2017. No MiT Records found.</u>	duranj	03/30/2018

**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401592622	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4419983">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4419983</a>
687901552	Lease sign	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4419900">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4419900</a>
687901553	Well pad	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4419901">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4419901</a>

687901554	Torn Liner	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4419902">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4419902</a>
687901555	Torn Liner	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4419903">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4419903</a>
687901556	Risers with to plugs,locks or L.O.T.O Tags	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4419904">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4419904</a>