

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

03/29/2018

Submitted Date:

04/03/2018

Document Number:

685304573**FIELD INSPECTION FORM**Loc ID 326093 Inspector Name: St John, William (Cal) On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 10133Name of Operator: HILCORP ENERGY COMPANYAddress: P O BOX 61229City: HOUSTON State: TX Zip: 77208**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:27 Number of Comments4 Number of Corrective Actions☒ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Hughes, Jim		jimo.hughes@state.co.us	
Leonard, Mike		mike.leonard@state.co.us	
Ray, Mandi	505-324-5122	mray@hilcorp.com	
Shorty, Priscilla		pshorty@hilcorp.com	
Roland, Kandis		kroland@hilcorp.com	
Trujillo, Etta		ettrujillo@hilcorp.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
215854	WELL	PR	02/02/1991	GW	067-07459	CARTER UTE 107	PR

General Comment:

Inspection completed as routine inspection inspection requirement.

This inspection does not alleviate requirement to complete any open corrective actions from previous inspections.

See link at end of report for path to downloadable pictures.

Location			
Lease Road:			
Type	Access		
comment:	Dirt and gravel access road.		
Corrective Action	L		Date:
Overall Good: <input type="checkbox"/>			
Signs/Marker:			
Type	CONTAINERS		
Comment:	Labels directly on Containers.		
Corrective Action:			Date:
Type	TANK LABELS/PLACARDS		
Comment:	Lables directly on tanks. Lables still identify ConocoPhillips as operator.		
Corrective Action:			Date:
Type	WELLHEAD		
Comment:	Metal sign on tank battery fencing.		
Corrective Action:			Date:
Emergency Contact Number:			
Comment:	Information inaccurate at well(s) or battery. There is no emergency contact number on wellhead sign. Using the phone number posted on tank as a ConocoPhillips contact number (505-324-5170) I spoke with Hilcorp representative.		
Corrective Action:	Signs need to be replaced or updated to reflect current operator as emergency contact to comply with Rule 210.b.(2).		Date: 05/03/2018
Good Housekeeping:			
Type	OTHER		
Comment:	Impacted soil and gravel on S and SW side of compressor unit.		
Corrective Action:	Non E&P Waste not properly stored, handled, transported, treated, or disposed per Rule 907A. Contact COGCC EPS staff.		Date: 04/06/2018
Type	DEBRIS		
Comment:	Silver insulation wrap debris in NW perimeter.		
Corrective Action:	Clean up and remove Debris to comply with Rule 603.f.		Date: 05/04/2018
Type	OTHER		
Comment:	Impacted soil and gravel on NW side of pump jack and along E side concrete base of pump jack.		
Corrective Action:	Clean up and remediate impacted soil and gravel to comply with Rule 906.a.		Date: 05/04/2018
Overall Good: <input type="checkbox"/>			
Spills:			
Type	Area	Volume	
In Containment: No			
Comment: <input type="text"/>			
<input type="checkbox"/> Multiple Spills and Releases?			
Fencing/:			
Type	TANK BATTERY		

Comment:	Steel post and hog wire fencing.			
Corrective Action:			Date:	
Equipment:				corrective date
Type: Compressor	# 1			
Comment:				
Corrective Action:			Date:	
Type: Gas Meter Run	# 1			
Comment:				
Corrective Action:			Date:	
Type: Bird Protectors	# 5			
Comment:	Tanks (3) Separator (2).			
Corrective Action:			Date:	
Type: Prime Mover	# 1			
Comment:	Natural gad motor.			
Corrective Action:			Date:	
Type: Flow Line	# 7			
Comment:	In use - 4" steel line from wellhead casing to separator inlet. All points co-located. In use - 3" steel line from wellhead casing to separator inlet. All points co-located. in use - 3" steel line from wellhead casing and tubing to separator inlet. All points co-located. In use - 4" steel line from wellhead casing and tubing to separator inlet. All points co-located. In use - 4" steel line from separator outlet to gas meter inlet. All points co-located. In use - 1" steel supply gas line from separator out let to wellhead all points co-located. In use - 1" steel supply gas line from separator outlet to tanks. All points co-located.			
Corrective Action:			Date:	
Type: Ancillary equipment	# 1			
Comment:	Telemetry equipment.			
Corrective Action:			Date:	
Type: Ancillary equipment	# 1			
Comment:	Lube oil tank with earthen berms (pump jack).			
Corrective Action:			Date:	
Type: Other	# 1			
Comment:	Lube oil tank with earthen berms (compressor).			
Corrective Action:			Date:	
Type: Other	# 1			
Comment:	Cathodic protection equipment.			
Corrective Action:			Date:	
Type: Dehydrator	# 4			
Comment:	Located (4) marked anchors.			
Corrective Action:			Date:	
Type: Ancillary equipment	# 1			
Comment:	Wellhead.			
Corrective Action:			Date:	

Type: Other	# 1	
Comment:	Steel carport (compressor cover).	
Corrective Action:		Date:
Type: Vertical Heated Separator	# 2	
Comment:	Well (1) Compressor (1).	
Corrective Action:		Date:
Type: Pump Jack	# 1	
Comment:		
Corrective Action:		Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	OTHER	Open Top		,
Comment:	Partially buried 120 BBL open top with expanded metal top and earthen berms.				
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)	120 BBLS	
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate	
Comment:					
Corrective Action:				Date:	
Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	3	500 BBLS	HEATED STEEL AST		,
Comment:	Above ground heated 500 BBL tanks with earthen berms. E tank is labeled as out of service.				
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities				
Facility ID: 215854	Type: WELL	API Number: 067-07459	Status: PR	Insp. Status: PR
Producing Well				
Comment:	PR - Review of electronic well file indicates last reported production as Dec 2017.			
Corrective Action:				Date:

--	--	--	--	--

Reclamation - Storm Water - Pit**Interim Reclamation:**

Date Interim Reclamation Started: _____ Date Interim Reclamation Completed: _____

Land Use: _____

Comment: Revegetation of interim reclamation area is progressing with established grass and Sage Brush.**1002 SITE PREPARATION AND STABILIZATION**

1002a. FENCING _____

Comment _____

Corrective Action _____

Date _____

1002b. SOIL REMOVAL AND
SEGREGATION _____

Comment _____

Corrective Action _____

Date _____

1002c. PROTECTION OF SOILS _____

Comment _____

Corrective Action _____

Date _____

1002E. SURFACE DISTURBANCE MINIMIZATION _____

Comment _____

Corrective Action _____

Date _____

1003a. Waste and Debris removed? Pass

Comment _____

Corrective Action _____

Date _____

Unused or unneeded equipment onsite? Pass

Comment _____

Corrective Action _____

Date _____

Pit, cellars, rat holes and other bores closed? Pass

Comment _____

Corrective Action _____

Date _____

Guy line anchors marked? Pass

Comment _____

Corrective Action _____

Date _____

1003b. Area no longer in use? _____ Production areas stabilized ? _____

1003c. Compacted areas have been cross ripped? _____

1003d. Drilling pit closed? _____ Subsidence over on drill pit? _____

Cuttings management: _____

1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? _____

Production areas have been stabilized? _____ Segregated soils have been replaced? _____

RESTORATION AND REVEGETATIONCropland

Top soil replaced _____ Recontoured _____ Perennial forage re-established _____

Non-Cropland

Top soil replaced _____ Recontoured _____ 80% Revegetation _____

1003e. INTERIM VEGETATION TRANSECT

TRANSECT RESULTS OF DISTURBED AREA% _____

TRANSECT RESULTS OF REFERENCE AREA% _____

TOTAL % OF DESIRABLE VEGETATION COVER _____

VEGETATIVE COVER _____

1003 f. Weeds Noxious weeds? _____

Comment _____

Corrective Action _____ Date _____

Overall Interim Reclamation**Final Reclamation/ Abandoned Location:**

Date Final Reclamation Started: _____ Date Final Reclamation Completed: _____

Final Land Use: _____

Reminder: _____

Comment: _____

Well plugged _____ Pit mouse/rat holes, cellars backfilled _____

Debris removed _____ No disturbance /Location never built _____

Access Roads _____ Regraded _____ Contoured _____ Culverts removed _____

Gravel removed _____

Location and associated production facilities reclaimed _____ Locations, facilities, roads, recontoured _____

Compaction alleviation _____ Dust and erosion control _____

Non cropland: Revegetated 80% _____ Cropland: perennial forage _____

Weeds present _____ Subsidence _____

1004.d. FINAL VEGETATION TRANSECT

TRANSECT RESULTS OF DISTURBED AREA% _____

TRANSECT RESULTS OF REFERENCE AREA% _____

TOTAL % OF DESIRABLE VEGETATION COVER _____

VEGETATIVE COVER _____

Comment: _____

Corrective Action: _____ Date _____

Overall Final Reclamation _____ Well Release on Active Location ☐ Multi-Well Location ☐

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Pass			
Compaction	Pass	Compaction	Pass	Material Handling And Spill Prevention	Pass	Lube oil tanks on spill prevention.

Comment: [Stormwater BMPs appear to be functioning at time of inspection.](#)

Corrective Action:

Date: _____

Pits: ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401595600	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4423367
685304586	Inspection pictures.	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4423360