

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

03/30/2018

Submitted Date:

04/03/2018

Document Number:

689800985

FIELD INSPECTION FORM

Loc ID 316739 Inspector Name: Waldron, Emily On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 52530
Name of Operator: MAGPIE OPERATING, INC
Address: 2707 SOUTH COUNTY RD 11
City: LOVELAND State: CO Zip: 80537

Findings:

- 8 Number of Comments
- 3 Number of Corrective Actions
- Corrective Action Response Requested

Contact Information:

| Contact Name | Phone | Email | Comment |
|--------------|-------|-------------------------|---------|
| Oil, Magpie | | magpieoil@yahoo.com | |
| Neidel, Kris | | kris.neidel@state.co.us | |

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|----------------------------|-------------|
| 232482 | WELL | PR | 03/01/2017 | OW | 107-05048 | RICHFIELD-WIRICK-FEDERAL 1 | PR |

General Comment:

[Routine FIU inspection.](#)

Location

Overall Good:

| Signs/Marker: | | | |
|----------------------|---|-------|------------|
| Type | TANK LABELS/PLACARDS | | |
| Comment: | Sign or label not posted or information inaccurate on tanks or containers. Insulated tank is not labeled. | | |
| Corrective Action: | Install sign to comply with Rule 210.d. | Date: | 05/03/2018 |
| Type | BATTERY | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type | WELLHEAD | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type | TANK LABELS/PLACARDS | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good:

| Spills: | | | |
|--------------------|---|--------|------------------|
| Type | Area | Volume | |
| PW/CO | WELLHEAD | | |
| Comment: | Inspector observed water, oil, absorbent pads, and trash floating in "pit" around wellhead. Operator was called by Inspector and EPS Kris Neidel, 3/30/2018 and informed of the 24 hour period to remove and properly dispose of free product. | | |
| Corrective Action: | E&P Waste not properly stored, handled, transported, treated, recycled, or disposed per Rule 907. Contact COGCC EPS staff. Remove free fluids and contact COGCC EPS staff per Rule 906.b. Provide on FIRR to this inspection estimated volume of oil, estimated volume of water, and source of the release. | | Date: 04/01/2018 |

In Containment: No

Comment:

Multiple Spills and Releases?

| Equipment: | | | corrective date |
|---------------------------------|----------------------|-------|-----------------|
| Type: Pump Jack | # 1 | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type: Vertical Heated Separator | # 1 | | |
| Comment: | 40.33840, -107.21851 | | |
| Corrective Action: | | Date: | |
| Type: Deadman # & Marked | # 4 | | |
| Comment: | | | |

| | | | |
|-----------------------|---|-------|--|
| Corrective Action: | | Date: | |
| Type: Bird Protectors | # | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

Tanks and Berms:

| Contents | # | Capacity | Type | Tank ID | SE GPS |
|--------------------|---|----------|-----------|---------|-----------------------|
| CRUDE OIL | 2 | 300 BBLs | STEEL AST | | 40.388400,-107.218510 |
| Comment: | | | | | |
| Corrective Action: | | | | | Date: |

Paint

| | |
|------------------|----------|
| Condition | Adequate |
| Other (Content) | |
| Other (Capacity) | |
| Other (Type) | |

Berms

| Type | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |
|--------------------|--|---------------------|---------------------|------------------|
| | Inadequate | Walls Insufficient | | Inadequate |
| Comment: | Inadequate berms around tank(s). No berm present. | | | |
| Corrective Action: | Repair or install berms or other secondary containment devices per Rule 605.a.(4). | | | Date: 05/03/2018 |

Venting:

| | |
|--------------------|-------|
| Yes/No | |
| Comment: | |
| Corrective Action: | Date: |

Flaring:

| | |
|--------------------|-------|
| Type | |
| Comment: | |
| Corrective Action: | Date: |

Inspected Facilities

Facility ID: 232482 Type: WELL API Number: 107-05048 Status: PR Insp. Status: PR

Producing Well

Comment: Pumping.

Corrective Action:

Date:

Reclamation - Storm Water - Pit

Storm Water:

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| | | | | | | |

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|----------------------|---|
| 401595880 | INSPECTION SUBMITTED | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4423654 |
| 689800986 | Inspection Photos | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4423653 |