

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

04/09/2018

Submitted Date:

04/10/2018

Document Number:

682600464**FIELD INSPECTION FORM**
 Loc ID 309599 Inspector Name: Kosola, Jason On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_
**Operator Information:**OGCC Operator Number: 16910Name of Operator: CHURCHILL ENERGY INCAddress: 8177 SOUTH NORFOLK STREETCity: ENGLEWOOD State: CO Zip: 80112**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**1 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Kluksdahl, Gary	(303) 840-7000, (303) 618-5025	gary.kluksdahl@comcast.net	
Axelson, John		john.axelson@state.co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
218178	WELL	PR	09/12/2013	OW	073-06163	CHAMPLIN-LIMON 2-19	EI

**General Comment:**

This is a follow up inspection to document status of COGCC Remediation 10302 which reclaimed an off pad release of sediment. Fencing around off pad release reclamation area was intact and no stormwater erosion issues were observed.

Operator should continue to inspect reclamation area after significant precipitation events as outlined in COA #3 in the approved remediation.

Photos attached to document site at the time of inspection.

**Inspected Facilities**Facility ID: 218178 Type: WELL API Number: 073-06163 Status: PR Insp. Status: EI**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
682600466	Inspection photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4428376">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4428376</a>