

**FORM  
INSP**

Rev  
X/15

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

03/12/2018

Submitted Date:

04/11/2018

Document Number:

688000146

**FIELD INSPECTION FORM**

Loc ID \_\_\_\_\_ Inspector Name: YOUNG, ROB On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

OGCC Operator Number: 14855  
Name of Operator: CENTRAL OPERATING INC  
Address: 1600 BROADWAY STE 1050  
City: DENVER State: CO Zip: 80202

**Findings:**

- 3 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

**Contact Information:**

Contact Name	Phone	Email	Comment
Axelson, John		john.axelson@state.co.us	
Cullin Johnson	303-894-9576	coidenverproduction@gmail.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
454308	SPILL OR RELEASE	AC	03/14/2018		-	Oil Tanks	AC

**General Comment:**

[Environmental inspection related to Spill ID 454308.](#)

**Inspected Facilities**

Facility ID: 454308 Type: SPILL OR API Number: - Status: AC Insp. Status: AC

**Environmental**

**Spills/Releases:**

Type of Spill: OIL Estimated Spill Volume: \_\_\_\_\_

Comment: Crew was on site and in the process of responding to the spill at the time of inspection. Please note the corrective action below, specifically the topo map or aerial photograph showing the location of the spill within 10 days.

Corrective Action: In addition to the Initial Report to the Director, the Operator shall make a supplemental report on Form 19 not more than 10 calendar days after the spill/release is discovered that includes an 8 1/2 x 11 inch topographic map showing the governmental section and location of the spill or an aerial photograph showing the location of the spill; all pertinent information about the spill/release known to the Operator that has not been reported previously; and information relating to the initial mitigation, site investigation, and remediation measures conducted by the Operator.

Date: 03/22/2018

Reportable: YES GPS: Lat \_\_\_\_\_ Long \_\_\_\_\_

Proximity to Surface Water: \_\_\_\_\_ Depth to Ground Water: \_\_\_\_\_

**Water Well Complaint:**

DWR Receipt Num: \_\_\_\_\_ Owner Name: \_\_\_\_\_ GPS : \_\_\_\_\_ Lat \_\_\_\_\_ Long \_\_\_\_\_

**Field Parameters:**

Sample Location: \_\_\_\_\_ Comment: \_\_\_\_\_

**COGCC Comments**

Comment	User	Date
Provide the topo map or aerial photograph of the spill location on a supplemental eForm 19 as soon as possible. Provide the soil sample laboratory data, soil sample location map and soil disposal manifests on a supplemental eForm 19 requesting NFA status once remaining soil within the tank battery meets Table 910-1 allowable levels.	youngr	04/11/2018

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
688000147	Location photographs	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4430557">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4430557</a>