

Inspection Photos

API: 05-067-07732

Operator: ENDURING RESOURCES LLC

Inspection Date: 3/21/2018



Photo 1. View of the project area from the northwestern corner facing center. Vegetation within the fenced in working area is largely comprised of cheatgrass (*Bromus tectorum*) and prickly lettuce (*Lactuca serriola*).



Photo 2. View of kochia (*Kochia scoparia*) debris along the western edge of the project area, outside of the fenced working area.



Photo 3. View of the southern portion of the project area from the southwestern corner facing eastward. Revegetation is progressing with grasses such as smooth brome (*Bromus inermis*) and intermediate wheatgrass (*Thinopyron intermedium*).



Photo 4. View of musk thistles (*Carduus nutans*) in the southern portion of the project area. Approximately 200 individuals observed.



Photo 5. Another view of musk thistles in the southern portion of the project area.



Photo 4. View of the eastern portion of the project area from the southeastern corner facing northward.