

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

04/04/2018

Submitted Date:

04/05/2018

Document Number:

689701241**FIELD INSPECTION FORM**Loc ID 334094 Inspector Name: LONGWORTH, MIKE On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 100185Name of Operator: ENCANA OIL & GAS (USA) INCAddress: 370 17TH ST STE 1700City: DENVER State: CO Zip: 80202-**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**7 Number of Comments3 Number of Corrective Actions☒ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Lujan, Carlos		carlos.lujan@state.co.us	
, Caerus Piceance		COGCC.inspections@caerus oilandgas.com	Piceance inspections only

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
275952	WELL	SI	09/01/2017	GW	045-10406	TIPPING 34-5 (OD34)	SI
275954	WELL	PR	12/01/2014	GW	045-10404	TIPPING 27-14 (OD34)	SI
275955	WELL	SI	09/01/2017	GW	045-10403	TIPPING 34-3 (OD34)	SI
281995	WELL	SI	09/01/2017	GW	045-11608	TIPPING 34-4X (OD34)	SI

General Comment:

LocationOverall Good: ☒

Signs/Marker:			
Type	CONTAINERS		
Comment:			
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Type	BATTERY		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment: 970-285-2615

Corrective Action:

Date: _____

Good Housekeeping:

Type	STORAGE OF SUPL		
Comment:	2 well head heaters on location. Heater flow tube laying at wellhead. Properly storage flow tube. Trash bin by the well head heaters and scrap iron dumpster by tank battery.		
Corrective Action:	Comply with Rule 603.f .	Date:	07/06/2018
Type	TRASH		
Comment:	Iron plumbing scraps and black tarps on the ground next to dumpster.		
Corrective Action:	Comply with Rule 603.f .	Date:	04/18/2018

Overall Good: ☒

Spills:			
Type	Area	Volume	
	Separator	<= 1 bbl	
Comment:	Fluid around flowlines behind separators has a sheen and oily texture. Appears bolt together flange is leaking. Carl Turnupseed was contacted from location to be made aware of spill/leak. He said he would send someone asap. COGCC Enviromental Specialist Carlos Lujan was contacted from location to be made aware of spill/leak. Caerus personel Bo Roland showed up to location to close in lines and trouble shoot.		
Corrective Action:	Contact COGCC EPS staff regarding Rule 906.c.		Date: 04/06/2018

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Fencing/:**

Type	LOCATION		
------	----------	--	--

Comment:			
Corrective Action:		Date:	
Equipment:			corrective date
Type: Gas Meter Run	# 5		
Comment:			
Corrective Action:		Date:	
Type: Plunger Lift	# 1		
Comment:			
Corrective Action:		Date:	
Type: Bird Protectors	# 2		
Comment:			
Corrective Action:		Date:	
Type: Vertical Heated Separator	# 4		
Comment:			
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS	
METHANOL	1	<50 BBLS	STEEL AST		,	
Comment:						
Corrective Action:						Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:	Date:			

Venting:

Yes/No	NO	
Comment:		
Corrective Action:		Date:

Flaring:

Type	
Comment:	
Corrective Action:	Date:

Inspected FacilitiesFacility ID: 275952 Type: WELL API Number: 045-10406 Status: SI Insp. Status: SI**Idle Well**Purpose: ☒ Shut In ☐ Temporarily Abandoned

Reminder: _____

Comment: Shut in since Aug 2017

Corrective Action: _____

Date: _____

Facility ID: 275954 Type: WELL API Number: 045-10404 Status: PR Insp. Status: SI**Idle Well**Purpose: ☒ Shut In ☐ Temporarily Abandoned

Reminder: _____

Comment: _____

Corrective Action: _____

Date: _____

Facility ID: 275955 Type: WELL API Number: 045-10403 Status: SI Insp. Status: SI**Idle Well**Purpose: ☒ Shut In ☐ Temporarily Abandoned

Reminder: _____

Comment: Shut in since Aug 2017

Corrective Action: _____

Date: _____

Facility ID: 281995 Type: WELL API Number: 045-11608 Status: SI Insp. Status: SI**Idle Well**Purpose: ☒ Shut In ☐ Temporarily Abandoned

Reminder: _____

Comment: _____

Corrective Action: _____

Date: _____

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Gravel	Pass			
Berms	Pass					
Gravel	Pass					
				Material Handling And Spill Prevention	Pass	
		Ditches	Pass			
Compaction	Pass					
Ditches	Pass					
		Compaction	Pass			
		Culverts	Pass			

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401597657	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4425402
689701242	Inspection 689701241 photo log	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4425401