

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

04/12/2018

Submitted Date:

04/13/2018

Document Number:

690100453**FIELD INSPECTION FORM**
 Loc ID 327377 Inspector Name: Maclaren, Joe On-Site Inspection ☐ 2A Doc Num: _____
Operator Information:OGCC Operator Number: 47120Name of Operator: KERR MCGEE OIL & GAS ONSHORE LPAddress: P O BOX 173779City: DENVER State: CO Zip: 80217-**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:2 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
,		cogccinspections@anadarko.com	
Schlagenhauf, Mark		mark.schlagenhauf@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
246794	WELL	PA	10/27/2014	GW	123-14591	CHAMPLIN 86 AMOCO Q 1	EG

General Comment:

Flowline Inspection Only. Photos uploaded can be accessed via link(s) at end of report.

Inspected FacilitiesFacility ID: 246794 Type: WELL API Number: 123-14591 Status: PA Insp. Status: EG**Flowline**

#1	Type:Non-Well Site	2 of Lines	
----	--------------------	------------	--

Flowline Description

Flowline Type: Non-Well Site Size: 3" Material: Fiberglass
 Variance: Age: Contents:

Integrity Summary

Failures: Spills: Repairs Made:
 Coatings: H2S: Cathodic Protection:

Pressure Testing

Witnessed: Test Result: Charted:

COGCC Rules(check all that apply)

☐ 1101. Installation and Reclamation ☐ 1102. Operations, Maintenance, and Repair ☒ 1103. Abandonment

Comment: COGCC Inspector met with Anadarko Personnel and contractors (Nail Services/ ENERGES) on site. Crews are in the process of removing (2) offsite flowlines that run 900' E-NE from the (PA) well to the battery (currently decommissioned); (1) 3" fiberglass production flowline and (1) 1" HDPE (black poly) gas supply line have been located and exposed by excavation/ hydro-excavation. The 3" fiberglass line is being flushed with fresh water to remove any remaining hydrocarbons. Trash flowline materials are being disposed of at an approved offsite facility. All flowlines associated with this well are being removed.

Corrective Action:

Date:

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
690100454	Crews work to expose and remove flowlines (to NE)	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4433094
690100455	Close up view of 3" and 1" flowline being removed	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4433095