

**FORM
INSP**Rev
X/15

State of Colorado

Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

04/12/2018

Submitted Date:

04/13/2018

Document Number:

691300106**FIELD INSPECTION FORM**

Loc ID 453075 Inspector Name: Kraich, Adam On-Site Inspection ☐ 2A Doc Num: _____

Operator Information:OGCC Operator Number: 10459Name of Operator: EXTRACTION OIL & GAS INCAddress: 370 17TH STREET SUITE 5300City: DENVER State: CO Zip: 80202**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
☐ FOLLOW UP INSPECTION REQUIRED
☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:5 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Kraich, Adam	970-420-0536	Adam.Kraich@state.co.us	(Area 117) Field Operations
,		COGCCInspections@extracti onog.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
453070	WELL	DG	01/22/2018		123-45901	Hergert South 35W-15-5N	DG

General Comment:

LocationOverall Good: ☐

Signs/Marker:			
Type	DRILLING/RECOMP		
Comment:	Adaquate		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action: Date:

Overall Good: ☒

Spills:					
Type	Area	Volume			

In Containment: No

Comment: ☐ Multiple Spills and Releases?

Fencing/:			
Type	LOCATION		
Comment:	Soundwalls, 36'		
Corrective Action:		Date:	

Venting:

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities

Facility ID: 453070 Type: WELL API Number: 123-45901 Status: DG Insp. Status: DG

Complaint

Comment: Inspection in response to complaint.

Field Inspector Assigned: Adam Kraich

Complaint Received:

Date: 4-12-2018

Complaint Contacted:

Date: 4-13-2018 Time 09:29 AM

Location #: 433075

Inspection Document #: 691300094

Nature of complaint: Noise

Field Inspector Actions:

On 4-12-2018, I was contacted by Jason Gomez of COGCC in reference to a sound complaint. The complainant stated the issues were coming from the Hergert 35-L Pad currently in the drilling process. (location ID 453075).

On 4-10-2018, I made contact with the drilling rig supervision and informed them of the nature of the complaint. They were aware of the noise issue as they were in process of tripping out of hole the evening prior, and experiencing mechanical issues while doing so. Per Extraction rig supervisors, they have corrected the issues.

I did not perform a sound study at time of inspection as there was a steady N/NE wind at 11mph.

On 4-13-2018, I made contact with the complainant, at approximately 9:29am. I informed him of the upset condition causing the above average noises. He understood and informed me that the noise seemed to subside, however it cannot be confirmed due to extremely high winds over the night and throughout the day.

No violation of COGCC rules were observed at the time of the inspection.

All information reviewed and site inspection information were submitted to the complaint specialist for further review.

Corrective Action:

Date:

Well Drilling

Rig: Rig Name: Patterson 364 Pusher/Rig Manager: _____
 Permit Posted: Yes Access Sign: Yes

Well Control Equipment:

Pipe Ram: _____ Blind Ram: _____ Hydril Type: _____
 Pressure Test BOP: _____ Test Pressure PSI: _____ Safety Plan: _____

Drill Fluids Management:

Lined Pit: _____ Unlined Pit: _____ Closed Loop: _____ Semi-Closed Loop: _____
 Multi-Well: _____ Disposal Location: _____

Comment:

Corrective Action:

Date:

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
691300108	Inspection photo	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4433392