

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

04/06/2018

Submitted Date:

04/09/2018

Document Number:

689300826**FIELD INSPECTION FORM**
 Loc ID 335102 Inspector Name: Holtz, Darin On-Site Inspection ☐ 2A Doc Num: _____
Operator Information:OGCC Operator Number: 10456Name of Operator: CAERUS PICEANCE LLCAddress: 1001 17TH STREET #1600City: DENVER State: CO Zip: 80202**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**11 Number of Comments2 Number of Corrective Actions☒ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Elsener, Garrett	(303)-565-4600	COGCC.inspections@caerusoilandgas.com	all Piceance inspections
,		mike.leonard@state.co.us	Mike Leonard

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
272024	WELL	PR	12/01/2004	GW	045-09998	GMR 34-3 (B34NW)	PR
272025	WELL	PR	11/23/2004	GW	045-09999	GMR 34-2 (B34NW)	PR
272026	WELL	PR	12/27/2004	GW	045-10000	GMR 34-1B (B34NW)	PR
272027	WELL	PR	11/29/2004	GW	045-10001	GMR 34-2B (B34NW)	PR

General Comment:[Routine Field Inspection](#)

Location

Lease Road:			
Type	Access		
comment:			
Corrective Action:		Date:	

Overall Good: ☒

Signs/Marker:			
Type	CONTAINERS		
Comment:	Labels missing on Chemical tote, Missing NFPA sign		
Corrective Action:	Install sign to comply with Rule 210.d. 2	Date:	06/06/2018
Type	OTHER		
Comment:	Missing Lease entrance sign		
Corrective Action:	Install sign to comply with Rule 210.b. 2	Date:	06/06/2018

Emergency Contact Number:

Comment: 1-800-791-7691

Corrective Action:

Date: _____

Good Housekeeping:

Type	TRASH		
Comment:			
Corrective Action:		Date:	
Type	WEEDS		
Comment:			
Corrective Action:		Date:	
Type	DEBRIS		
Comment:			
Corrective Action:		Date:	

Overall Good: ☒

Spills:				
Type	Area	Volume		

In Containment: No

Comment:

☐ Multiple Spills and Releases?

Equipment:			corrective date
Type: Ancillary equipment	# 2		
Comment:			
Corrective Action:		Date:	
Type: Deadman # & Marked	# 10		
Comment:			
Corrective Action:		Date:	

Type: Emission Control Device	# 1		
Comment:			
Corrective Action:			Date:
Type: Plunger Lift	# 4		
Comment:			
Corrective Action:			Date:
Type: Vertical Heated Separator	# 11		
Comment:			
Corrective Action:			Date:
Type: Bird Protectors	# 5		
Comment:			
Corrective Action:			Date:
Type: Gas Meter Run	# 1		
Comment:			
Corrective Action:			Date:
Type: Flow Line	# 1		
Comment:			
Corrective Action:			Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS	
CONDENSATE	4	500 BBLs	STEEL AST		,	
Comment:						
Corrective Action:						Date:

Paint

Condition	Adequate	
Other (Content)	Methanol Tank	
Other (Capacity)	24 BBL	
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				
			Date:	

Venting:

Yes/No	NO	
Comment:		
Corrective Action:		
		Date:

Flaring:

Type	
Comment:	

Corrective Action:		Date:	
--------------------	--	-------	--

Inspected Facilities									
Facility ID:	272024	Type:	WELL	API Number:	045-09998	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Well Producing on plunger lift Last production numbers posted as of Oct. 2017								
Corrective Action:						Date:			
Facility ID:	272025	Type:	WELL	API Number:	045-09999	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Well Producing on plunger lift Last production numbers posted as of Oct. 2017								
Corrective Action:						Date:			
Facility ID:	272026	Type:	WELL	API Number:	045-10000	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Well Producing on plunger lift Last production numbers posted as of Oct. 2017								
Corrective Action:						Date:			
Facility ID:	272027	Type:	WELL	API Number:	045-10001	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Well Producing on plunger lift Last production numbers posted as of Oct. 2017								
Corrective Action:						Date:			

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction		Gravel	Pass			
Berms		Compaction	Pass	Vehicle Tracking		

Comment: [Rutted location](#)

Corrective Action:

Date: _____

Pits: ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401600289	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4428238
689300827	DocNum: 689300826.4/5/18	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4428219