

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

04/11/2018

Submitted Date:

04/11/2018

Document Number:

675000340**FIELD INSPECTION FORM**

Loc ID 327850 Inspector Name: Duran, Alicia On-Site Inspection ☐ 2A Doc Num: _____

Operator Information:OGCC Operator Number: 100322Name of Operator: NOBLE ENERGY INCAddress: 1001 NOBLE ENERGY WAYCity: HOUSTON State: TX Zip: 77070**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**5 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**Contact Information:**

| Contact Name | Phone | Email | Comment |
|--------------|-------|----------------------------------------|---------|
| , | | NBL_DJBU_Inspections@NB LENERGY.COM | |

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|----------------|-------------|
| 426853 | WELL | SI | 09/01/2017 | OW | 123-34801 | SHABLE G17-24D | SI |

General Comment:

LocationOverall Good: ☒

| | | | |
|----------------------|----------|-------|--|
| Signs/Marker: | | | |
| Type | WELLHEAD | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

| | |
|---------------------------|-------------|
| Emergency Contact Number: | |
| Comment: | |
| Corrective Action: | Date: _____ |

| | | |
|---------------------------|------------------------------------|------------------|
| Good Housekeeping: | | |
| Type | WEEDS | |
| Comment: | Weeds around wellhead. See photos. | |
| Corrective Action: | Comply with Rule 603.f | Date: 04/21/2018 |

Overall Good: ☐

| | | | | |
|----------------|------|--------|--|--|
| Spills: | | | | |
| Type | Area | Volume | | |

In Containment: No

Comment: _____

☐ Multiple Spills and Releases?

| | | |
|--------------------|----------|-------|
| Fencing/: | | |
| Type | WELLHEAD | |
| Comment: | Panel | |
| Corrective Action: | | Date: |

| | | | |
|--------------------|-----|-------|-----------------|
| Equipment: | | | corrective date |
| Type: Plunger Lift | # 1 | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

| | | | | | |
|-------------------------|-------------------------------------|----------|---------------------|---------|-----------------------|
| Tanks and Berms: | | | | | |
| Contents | # | Capacity | Type | Tank ID | SE GPS |
| | | | CENTRALIZED BATTERY | | 40.307690,-104.682280 |
| Comment: | Shared facility with API# 123-15235 | | | | |
| Corrective Action: | | | | Date: | |

| | |
|------------------|--|
| Paint | |
| Condition | |
| Other (Content) | |
| Other (Capacity) | |
| Other (Type) | |

| | |
|---------------------|---------------------|
| Berms | |
| Type | Capacity |
| Permeability (Wall) | Permeability (Base) |
| Maintenance | |

| | | | | | |
|------------------------|--|--|--|--|-------------------|
| | | | | | |
| Comment: | | | | | |
| Corrective Action: | | | | | Date: <div></div> |
| <u>Venting:</u> | | | | | |
| Yes/No | | | | | |
| Comment: | | | | | |
| Corrective Action: | | | | | Date: <div></div> |
| <u>Flaring:</u> | | | | | |
| Type | | | | | |
| Comment: | | | | | |
| Corrective Action: | | | | | Date: <div></div> |

Inspected FacilitiesFacility ID: 426853 Type: WELL API Number: 123-34801 Status: SI Insp. Status: SI**Idle Well**Purpose: ☒ Shut In ☐ Temporarily Abandoned Reminder: _____Comment: SI

Corrective Action: _____ Date: _____

BradenHeadComment: Plumbed to surface

Corrective Action: _____ Date: _____

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|----------------------|---------------------------------------------------------------------------------------------------------------------------------------------------------------------|
| 401605075 | INSPECTION SUBMITTED | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4431080 |
| 675000349 | Photos of wellhead | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4431070 |